

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-27915
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name ELKAN
2. Name of Operator ELK OIL COMPANY	8. Well No. 2
3. Address of Operator Post Office Box 310, Roswell, New Mexico 88202-0310	9. Pool name or Wildcat Scharb Bone Spring
4. Well Location Unit Letter <u>O</u> : <u>660</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>East</u> Line Section <u>9</u> Township <u>19 South</u> Range <u>35 East</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3808.9' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plug and Abandon well as follows, on October 28, 1991:

- (1) Spot 20 sxs at 5739' - 5561' tagged.
- (2) Spot 25 sxs at 2000' - 1800'.
- (3) Spot 10 sxs at 50' to surface.
- (4) Install dry hole marker.
- (5) Hole circulated with 10# mud.

Location cleaned and ready for inspection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE President DATE 12/09/92
TYPE OR PRINT NAME Joseph J. Kelly TELEPHONE NO. 505/623-3190

(This space for State Use)

APPROVED BY [Signature] TITLE OIL & GAS INSPECTOR DATE DEC 15 '92
CONDITIONS OF APPROVAL, IF ANY: