

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240  
DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210  
DISTRICT III  
000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-27943
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. LG-740-3
7. Lease Name or Unit Agreement Name Vacuum State
8. Well No. 1
9. Pool name or Wildcat Scharb Bone Springs

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER P & A Well
2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210
4. Well Location Unit Letter J : 1980 Feet From The South Line and 1980 Feet From The East Line

Section 4	Township 19S	Range 35E	NMPM	Lea	County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)					

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
WELL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged and abandoned well as follows:

Moved in and rigged up pulling unit. POOH w/pump, rods, tubing anchor and tubing. WIH w/5-1/2" CIBP and set at 9450'. Capped with 35' of cement on top of CIBP. RIH w/tubing. Loaded hole with mud. Spotted a 35 sack cement plug at 5400'. Perforated 4 holes at 3998'. Picked up 5-1/2" retainer and set at 3950'. Unable to squeeze. Pressured up at 2000#. Contacted NMOCD - Hobbs. Spot 25 sacks cement on top of retainer. POOH w/tubing. Perforated 4 shots at 503'. Broke circulation between 5-1/2" and 8-5/8" annulus with 60 bbls water. Bullhead squeeze with 50 sacks cement down casing leaving 100' of cement. Set at 25 sack surface plug. PLUGGED AND ABANDONED - FINAL REPORT.

Plugging complete August 5, 1993.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE Sept. 7, 1993  
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

APPROVED BY Johnny Robinson TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

SEP 8 1993

WORLD HISTORY  
OFFICE