

DISTRICT I

1625 N. French Dr., Hobbs, NM 88240

DISTRICT II

811 S. First Street, Azusa, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 South Pacheco  
Santa Fe, New Mexico 87505

WELL API NO.  
30-025-27988

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

SNYDER RANCH

8. Well No.

1

9. Pool Name or Wildcat

BRUSHY CANYON

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL ☐ GAS ☐  
WELL ☒ WELL ☐ OTHER

Name of Operator

ELK OIL COMPANY

3. Address of Operator

POST OFFICE BOX 310, ROSWELL, NEW MEXICO 88202-0310

4. Well Location

Unit Letter H : 1980 Feet From The NORTH Line and 660 Feet From The EAST Line

Section 8 Township 19 SOUTH Range 35 EAST NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3862' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETION ☐

OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)

SEE RULE 1103 For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

January 7-15, 2003: Pull out of hole with rods and tubing. Run in hole with CIBP, set at 10,430' with 35' cement.  
Perforated 7596'-7605', 24 holes. Acidize with 1500 gallons 7 1/2 Ferchek, swab back load. Prepare to frac.

January 20-February 3, 2003: Frac with 22,000 gallons gelled H2O with 35,000 pounds sand. Swabbed back load plus 200  
barrels water, no shows. Pull out of hole with tubing and packer. Run in hole with CIBP, set at 7470' with 35' cement.  
Perforated 5152'-5162' 20 holes. Acidize with 1500 gallons 7 1/2% Ferchek. Swabbed load with no shows. Prepare to plug and  
abandon.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

PRESIDENT

TYPE OR PRINT NAME

JOSEPH J. KELLY

DATE 2/3/03

TELEPHONE NO. 505-623-3190

(This space for State Use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

ORIGINAL SIGNED BY

GARY W. WINK

OC FIELD REPRESENTATIVE II/STAFF MANAGER

FEB 04 2003

