

L CONSERVATION DIVIS
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.

A-4096

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER-	7. Unit Agreement Name
2. Name of Operator EXXON CORPORATION	8. Farm or Lease Name NEW MEXICO DD STATE
3. Address of Operator BOX 1605, MIDLAND, TEXAS 79702	9. Well No. 5
4. Location of Well UNIT LETTER D 660 FEET FROM THE NORTH LINE AND 660 FEET FROM THE WEST LINE, SECTION 4 TOWNSHIP 19S RANGE 35E NMDM.	10. Field and Pool, or Wildcat SCHARB-BONESPRING
11. Elevation (Show whether DF, RT, GR, etc.) 3917 ER	12. County LEA

13. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☒	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPER. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- PULL RODS AND TUBING.
- RIH W/OPENED TUBING TO 9700'. CIRC. FULL OF 3% KCL WTR.
- SQUEEZE PERFS 9372-9686 w/90 SACKS CLASS "H" NEAT.
- DRILL OUT CMT TO 9560'. TEST TO 500 PSI.
- SET LK-SET PRR AT 9420'. TEST TBB TO 5000 PSI. SET PRR-TEST TO 500 PSI.
- PERF 5 1/2" CSG 9520-9550 W/4 SPF.
- SWAB TEST.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED L. F. Lowe TITLE S. R. ADAMS DATE 1-29-84

APPROVED BY RECEIVED TITLE RECEIVED DATE 1-29-84

CONDITIONS OF APPROVAL, IF ANY: