

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-28056 ✓
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-2317
7. Lease Name or Unit Agreement Name M. E. Hale
8. Well No. 13
9. Pool name or Wildcat Vacuum Gb/SA
10. Elevation (Show whether DP, RKB, RT, GR, etc.) 4011' GL; 4022' RKB

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Water Injection
2. Name of Operator Phillips Petroleum Company
3. Address of Operator 4001 Penbrook Street, Odessa, TX 79762
4. Well Location Unit Letter I : 1360 Feet From The South Line and 1210 Feet From The East Line Section 35 Township 17-S Range 34-E NMPM Lea County
10. Elevation (Show whether DP, RKB, RT, GR, etc.) 4011' GL; 4022' RKB

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: Started Injection ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-12-93 - MIRU to run step rate test:  
Start pump - 1 BPM - Press 1700#.  
Stop pump after 15 bbls. - Press 1950#.  
Start Pump - 2 BPM - Press 1700#.  
Stop pump after 30 bbls. - Press 2050#.  
Start pump 3 BPM - Press 1700#.  
Stop pump after 45 bbls. - Press 2350#.  
Start pump 4 BPM - Press - 1700#.  
Stop pump after 27 bbls. - Press 2500#  
PUT WELL ON INJECTION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. M. Sanders TITLE Supv., Regulatory Affairs DATE 03-24-93  
TYPE OR PRINT NAME L. M. Sanders TELEPHONE NO. (915)368-1488

(This space for State Use)

ORIGINAL SENT TO: VERY SECTION  
BY: [Signature]

MAR 30 1993

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED  
MAR 2 9 1993  
OCD HOBBS OFFICE