

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name	
2. Name of Operator Carr Well Service, Inc.		8. Farm or Lease Name Cooper	
3. Address of Operator Box 6427, Odessa, Texas 79767-6427		9. Well No. #1	
4. Location of Well UNIT LETTER <u>C</u> <u>338</u> FEET FROM THE <u>North</u> LINE AND <u>1784</u> FEET FROM THE <u>West</u> LINE, SECTION <u>2</u> TOWNSHIP <u>17-S</u> RANGE <u>38-E</u> N.M.P.M.		10. Field and Pool, or Wildcat <u>Kenneth R. Brown</u>	
15. Elevation (Show whether DF, RT, GR, etc.)		12. County Lea	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 2/27/87 Set 5 1/2 C.I.B.P. @ 10798 w/2 sx
- 2/27/87 Set 25 sx plug @ 10346 - 10120
- 3/01/87 Set 105 sx plug @ 6997 Tag at 6341
- 3/02/87 Set 40 sx plug @ 6341 to 5946
- 3/02/87 Set 120 sx plug @ 5053 Tag @ 4800
- 3/02/87 Set 20 Sx plug @ 4800 to 4750
- 3/02/87 Set 40 sx plug @ 2150 to 2050
- 3/02/87 Set 10 sx plug @ 30' to surface.

Circ hole w/mud

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Ruby Swinick TITLE Cementer DATE 03/03/87

APPROVED BY Cindy E. Howard TITLE Agent DATE 03/03/87

CONDITIONS OF APPROVAL, IF ANY
Approved by [Signature] TITLE OIL & GAS INSPECTOR DATE APR 14 1987