

UNITED STATES ~~HOBBS, NEW MEXICO~~ ^{ROSWELL, NEW MEXICO}
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well gas ☐ well other ☐
2. NAME OF OPERATOR
The Superior Oil Company
3. ADDRESS OF OPERATOR
P.O. Box 3901, Midland, Texas 79702
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1980' FSL, 660' FEL, Sec. 9
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH: Same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐

(other) Weekly Drilling Recap.

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☐
☐
☐

RECEIVED

JUN 1 1983

OIL & GAS

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

4-11-83 Spudded @ 4:30 P.M., drld rat hole, set 20" csg. @ 40'.
4-12-83 MI Resource Rig #23.
4-13-83 MI Rig.
4-14-83 Drld to 430', svy @ 430' = $\frac{1}{2}^\circ$, running 13 3/8' csg.
4-15-83 Ran 13 3/8" csg, set @ 430', drld cmt.
4-16-83 Drld to 1792', svy @ 890' = $\frac{1}{2}^\circ$, @ 1380' = $\frac{3}{4}^\circ$.
4-17-83 Drld to 2819', svy @ 2339' = $\frac{3}{4}^\circ$.
4-18-83 Drlg @ 3440', svy @ 2881' = $\frac{3}{4}^\circ$, @ 3406' = $\frac{3}{4}^\circ$.
4-19-83 Drlg @ 3693'. Svy @ 3546' = 1° .
4-20-83 Drlg @ 4073'.
4-21-83 Drld to 4135', circ & cond hole, ran and cmtd 9 5/8" csg, set @ 4135'.
4-22-83 WOC, tested equip, drld hard cmt.

Subsurface Safety Valve: Manu. and Type

Set @ (Over) Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED G. E. Tate TITLE Area Prod. Supt. DATE 5-31-83

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

R. S. D.
JUL 12 1983

*See Instructions on Reverse Side

ROSWELL, NEW MEXICO

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

GPO : 1981 O - 347-166

4-23-83 Drld to 4612' Svy @ 4135' = 1°.
4-24-83 Drld to 4612' Svy @ 4634' = 3/4°.
4-25-83 Drld to 5464' Svy @ 5128' = 1°.
4-26-83 Drld to 5464' Svy @ 5622' = 1°.
4-26-83 Drld to 5464' Svy @ 5899' = 1°.
4-27-83 Drld to 6400' Svy @ 6106' = 1°.
4-28-83 Drld to 6542' tested equip. Svy @ 6542' = 1°.
4-29-83 Drld to 7046' Svy @ 6945' = 1°.
4-30-83 Drld to 7680' Svy @ 7459' = 1°.

RECEIVED
OCCD
MOBBS OFFICE
JAN 14 1983