

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
I. Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer 00, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-28241
1. Indicate Type of Lease	STATE ☒ FEED ☐
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
Chevron U.S.A. Inc.

3. Address of Operator
P.O. Box 670, Hobbs, NM 88240

4. Well Location
Unit Letter B : 460 Feet From The North Line and 1980 Feet From The East Line
Section 16 Township 19S Range 35E NMPM Lea County

7. Lease Name or Unit Agreement Name

Lea "TZ" State

8. Well No.
2

9. Pool name or Wildcat
Scharb/Bone Spring

10. Elevation (Show whether OF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NOTIFY NM OCD 24 HRS PRIOR TO START OF P&A OPERATIONS @ 393-6161
MIRU PU TIH W/OE TBG SPOT P&A MUD F 9615 TO 6000± RU WL CO. & RUN FREE POINT INDICATOR
SET CIBP @ 9550' CAP W/35' CMT TEST CSG TO 500 PSI
CUT & PULL 5 1/2" CSG AS REQUIRED (INSTALL THREAD PROTECTORS)
SET 200' CMT PLUG ACROSS 5 1/2" CSG STUB (100' INSIDE & 100' OUTSIDE)
SET 200' CMT PLUG ACROSS SAN ANDRES F 5364' TO 5164'
SET 200' CMT PLUG ACROSS 9 5/8" CSG SHOE F 4365 TO 4165
SET 200' CMT PLUG ACROSS TOP OF ANHY F 1932' TO 1732'
SET 60' CMT PLUG FROM 60' TO SURFACE
INSTALL DRY HOLE MARKER
CHANGE STATUS TO PLUG & ABANDONED

**P&A MUD TO BE PLACED BETWEEN ALL CMT PLUGS
***SEE ATTACHED SHEET FOR FORMATION TOPS

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE M. E. Akins 8/10/90 TITLE Staff Drlg. Engr. DATE 8-10-90

TYPE OR PRINT NAME M. E. Akins

TELEPHONE NO. 393-4121

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

AUG 17 1990