

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-28257
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	LG-740-3
7. Lease Name or Unit Agreement Name	
Vacuum State	
8. Well No.	4
9. Pool name or Wildcat	Scharb Bone Springs

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER PLUG & ABANDON
2. Name of Operator	YATES PETROLEUM CORPORATION
3. Address of Operator	105 South 4th St., Artesia, NM 88210
4. Well Location	Unit Letter I : 1980 Feet From The South Line and 660 Feet From The East Line
Section 4	Township 19S Range 35E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-8-95 - Moved in and rigged up pulling unit.

8-9-95 - Nippled up BOP. Released packer. POOH with tubing and packer. Rigged up wireline. TIH with 5-1/2" CIBP and set at 9400'. Rigged down wireline. TIH with tubing to 9400'. Spotted 141 bbls plug mud from 9400-3900' (in 5-1/2" casing). Mixed and pumped 25 sacks Class H cement from 9400-9200' (in 5-1/2" casing). POOH with tubing to 1741'. Shut down for night.

8-10-95 - Loaded well with water. Pumped 220 bbls - would not load. TIH with tubing and tagged CIBP at 9400'. POOH with tubing. Rigged up wireline. TIH with 5-1/2" CIBP and set at 9200'. Loaded well - stayed loaded. TIH with tubing to 9200'. Shut down for night.

8-11-95 - Spotted 126 bbls plug mud from 9200-3900'. Mixed and pumped 25 sacks Class C cement from 9200-9000'. POOH with tubing to 7741'. Mixed and pumped 25 sacks Class C cement from 7741-7541' (in 5-1/2" casing). POOH with tubing to 5398'. Mixed and pumped 25 sacks Class C cement from 5398-5198'. POOH with tubing. Rigged up wireline. TIH and cut 4-1/2" casing at 4050'. Rigged down wireline. Nippled down BOP and wellhead.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

CONTINUED ON NEXT PAGE:

SIGNATURE Rusty Klein TITLE Production Clerk DATE Aug. 18, 1995
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

OIL & GAS INSPECTOR

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

NOV 19 1905

U.S. DEPT. OF AGRICULTURE

WASHINGTON