## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

WB. BF COPIES SECTIVES		
DISTRIBUTION	1	
SANTA FE		
FILE		
U.\$.G.\$,		
LAND OFFICE		
OPERATOR	1	ī —

## LL CONSERVATION DIVISION

SANTA FE	P. O. BO			Form C-103 Revised 19-1-1	
FILE	SANTA FE, NEW	MEXICO 87501			
U.\$.G.\$,	]		50. Indicate Type of Lea		
LAND OFFICE	4	_	State	Fee X	
OPERATOR	J	•	5. State Ot: 6 Gas Lease	* No.	
COMITS	OV NOTICES AND DEBORTS ON	WELLS	mmmm	mm	
SUNDT USE THIS FORM FOR PRO USE "TAPPLICAT	RY NOTICES AND REPORTS ON	WELLS FACE TO A DIFFERENT RESERVOIR, H PROPOSALS I			
			7. Unit Agreement liana	777777	
well well X	OTHER-				
, Name of Operator	_		E. Farm or Lease Name		
	l Producers, Inc.	•	Fee KJ		
I, Address of Operator			9. Well No.		
P.O. Box 14	498 Roswell, New Mexico	88201	#1		
· -	660 FEET FROM THE South	LINE AND 1980 FE	10. Field and Pool, or W Wildcat	Hdcat	
				THE STATE OF THE SECOND PARTY.	
THE West LINE, SECTION	on 3 TOWNSHIP 19S	RANGE 35E	_NMPM.		
mmmmm	15. Elevation (Show whether	Dr pr cp		###	
	3853.4	Dr. KI, GR. etc.)	12. County		
	******		Lea	777777	
	Appropriate Box To Indicate N				
NOTICE OF IN	NTENTION TO:	SUBSE	QUENT REPORT OF:		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	HEMEDIAL WORK			
TEMPORARILY ABANDON	7250 246 222001	COMMENCE DRILLING OPHS.	ALTERING CASI	<u>}</u>	
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	<del>==</del> {	004×241 [	
		OTHER			
OTHER					
2. Describe Proposed or Completed Or	perations (Clearly state all pertinent deta	ile and sine participat datas i	al. Jim astimated date of sension		
work) SEE RULE 1703.	resections (clearly state are pertment det	ins, and give pertinent dutes, t	ictuating estimated date of starting	any propose	
8-20-85 Rig up rotar	ry drilling rig, prepared	to re-enter well a	9:00 PM		
<u>8-21-85</u> Tagged first	plug 25' below surface				
8-26-85 Reached orig					
8-29-85 Drilled to r	new TD of 11,143', missed	Wolfcamp pay zone,	planning to log botto	om	
portion of t	the hole and move rig off	, will plug bottom	portion if necessary	and	
8-30-85 Lav down dri	complete Queen formation.				
$\frac{9-5-85}{9-5-85}$ Move in pull	ll pipe and set plugs, m	oved off rig and le	t hole open to 9700'		
<del></del>	ing unit, rig up Wellex, s, picked up TST packer.	ran tie-in log, per	riorated 4614'-4624' -	-	
9-6-85 Set packer at	2 4625!				
	ourton, acidize with 1000	gallons 15% NE with	n 30 hall sealers ever	cv 100	
gallons, swab	well, well kicked off a	nd flowing gas.		<b>y</b> 100	
9-9-85 Testing well,	released rig, left well	flowing over night	with 24/64 choke.		
9-10-85 180 psi on tu	ıbing, 86 bbls. on bucket	t test.			
9-25-85 well shut in,	wait on Phillips.				
		•			
		·			
B. I hereby certify that the information	above is true and complete to the best o	if my knowledge and belief.			
$\cdot$	(a) (b) (b) (c)		•		

11 Eddie W. Soay 1 Agent Oil & Gas Inspector"

NOV 22 1985