

CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

|                        |  |
|------------------------|--|
| NO. OF COPIES RECEIVED |  |
| DISTRIBUTION           |  |
| SANTA FE               |  |
| FILE                   |  |
| U.S.G.S.               |  |
| LAND OFFICE            |  |
| OPERATOR               |  |

5a. Indicate Type of Lease  
State ☒ Fee ☐  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG A WELL TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

|                                                                                                                                                                                                             |                                                             |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>                                                                                            | 7. Unit Agreement Name                                      |
| 2. Name of Operator<br>Getty Oil Company                                                                                                                                                                    | 8. Farm or Lease Name<br>Scharb 10 State                    |
| 3. Address of Operator<br>P. O. Bpx 728, Hobbs, New Mexico 88240                                                                                                                                            | 9. Well No.<br>1                                            |
| 4. Location of Well<br>UNIT LETTER <u>L</u> , <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>10</u> , TOWNSHIP <u>19-S</u> , RANGE <u>35-E</u> NMPM. | 10. Field and Accy. or Wildcat<br>Undesignated Bone Springs |
| 11. Elevation (Show whether DF, RT, GR, etc.)<br>3122.1 GR                                                                                                                                                  | 12. County<br>Lea                                           |

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

|                                                |                                           |                                                     |                                                          |
|------------------------------------------------|-------------------------------------------|-----------------------------------------------------|----------------------------------------------------------|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/>              | ALTERING CASING <input type="checkbox"/>                 |
| TEMPORARILY ABANDON <input type="checkbox"/>   | CHANGE PLANS <input type="checkbox"/>     | COMMENCE DRILLING OPNS. <input type="checkbox"/>    | PLUG AND ABANDONMENT <input checked="" type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/>  | OTHER <input type="checkbox"/>            | CASING TEST AND CEMENT JOB <input type="checkbox"/> |                                                          |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rigged up.
2. Perforated 5½" Casing W/2 JSPF 9469-9548' (20 holes).
3. Acidized perfs 9469-9548' W 12-3 HCL-HF & 50 ball sealers.
4. Swabbed well non-productive prepare to P&A.
5. Rigged up.
6. Set cmt. retainer & squeezed W/150 sxs "H" Neat at 9469'-9620'.
7. TIH to 9230'. Displaced W/200 bbl. 10# brine & salt gel. Spotted 32 Sxs. class "H" neat from 8958'-9230'.
8. Spotted 20 sxs class "H" Neat from 4005-4152'. Spotted 20 sxs class "H" Neat from 1753-1900'. Spotted 10 sxs class "H" Neat to surf. Rigged down. Installed dry hole marker & cleaned location. P&A 3-9-85.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W.B. Lh TITLE Dist. Opr. Mgr. DATE March 13, 1985

APPROVED BY Ronald M. Allthorpe OIL & GAS INSPECTOR DATE AUG 27 1985

CONDITIONS OF APPROVAL, IF ANY: