

DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

SAT. 8/20/83
 0+6-NMOCD-H
 1-File
 1-Engr PJB
 1-Foreman HS
 1-Mr. J.A. Admin. Unit-Mid.
 1-BB
 1-JA

Form 6
 REVISED
 1. State ☒ State of New Mexico
 2. State Oil & Gas Lease No.
 750469

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO CEASE OR PLUG BACK A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM 6-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator Getty Oil Company	8. Farm or Lease Name Scharb 10 State
3. Address of Operator P.O. Box 730, Hobbs, NM 88240	9. Well No. 1
4. Location of Well UNIT LETTER L 1980 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 10 TOWNSHIP 19S RANGE 35E N.M.P.M.	10. Field and Pool, or Wildcat Wolfcamp-Undesignated
15. Elevation (Show whether DF, RT, GR, etc.) 3122.1 G.L.	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
 TEMPORARILY ABANDON ☐
 PULL OR ALTER CASING ☐
 OTHER ☐
 PLUG AND ABANDON ☐
 CHANGE PLANS ☐
 OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIATION WORK ☐
 COMMENCE DRILLING OPERATIONS ☐
 CASING TEST AND CEMENT JOBS ☒ Drlg.
 OTHER ☒
 ALTERING CASING ☐
 PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8/23/83 7 7/8" hole @ 4100'. Ran 93 jts of 8 5/8", S-80, 28# csg (4074') & 1 jt of 8 5/8" K-55, 24# (8'), total of 4082' and set @ 4100'. By Western cmt w/ 1250 sxs of pacesetter lite "C" w/ 10# of salt per sx and 5# gilsonite per sx and 1/4" cello-seal per sack. Tailed in w/ 250 sxs of class "C" neat w/ 2% CC. Circ. approx. 150 sxs.

9/15/83 Hole @ 10793'. Ran 40 jts of S-95, 17# (1563'), 106 jts of 17#, L-80 (4519') and 15 jts of K-55, 17# (621') and 104 jts of K-55, 15.5# (4115'), total of 10775' csg. Csg set @ 10793'. FC @ 10751'. DV @ 6027'. By Western cmt 1st stage w/ 950 sxs of 50/50 poz "H" w/ .7% CF-1, .2% AF-HD, 1/4# cello-seal per sx. Bump plug on 1st stage @ 2:45 P.M. w/ 2000#, drop bomb and open DV tool. Circ. w/ rig pump for 6 hours. Circ. approx. 70 sxs on 1st stage. 2nd stage. Cmt w/ 675 sxs of pacesetter lite "C", w/ 1/4# cello-seal per sx. Tail in w/ 200 sxs of class "H" w/ .4% CF-1. Bump plug @ 9:45 P.M. w/ 2250#. Circ. 90 sxs. Pick up BOP and set slips. Test head to 3200#, OK. Rig down. Waiting on completion rig.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED D.R. Crockett TITLE Area Superintendent

DATE September 20, 1983

APPROVED BY ORIGINAL SIGNED BY JERRY SEXTON
 CONDITIONS OF APPROVAL DISTRICT SUPERVISOR

DATE SEP 26 1983