

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-28426
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☐ GAS WELL ☐ OTHER ☐ Injector	7. Lease Name or Unit Agreement Name Bridges State
2. Name of Operator Mobil Producing TX & NM Inc.* *Mobil Exploration & Producing US Inc. as agent for MPTM	8. Well No. 185
3. Address of Operator P.O. Box 633, Midland, TX 79702	9. Pool name or Wildcat Vacuum Grayburg (San Andres)
4. Well Location Unit Letter <u>E</u> : <u>2628</u> Feet From The <u>North</u> Line and <u>100</u> Feet From The <u>West</u> Line Section <u>25</u> Township <u>17-S</u> Range <u>34-E</u> NMPM Lea County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL 4003

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- MIRU PU. DIG PIT. FLOW WELL BACK TO PIT. ND WH. NU BOP.
- POOH W/ 144 JTS 2-3/8" J-55 FLUORLINE TBG & 5-1/2" BAKER AD-1 PACKER & LD. RIH W/ CICR & WS TO 4400'. SET CICR @ 4400' AND CAP W/ 35' CLASS C NEAT CMT. LOAD HOLE W/ 10 PPG GELLED BRINE.
- PUH TO 2920'. SPOT 25 SX CLASS C NEAT CMT PLUG ACROSS YATES TOP @ 2870' FROM 2920-2820'.
- PUH TO 1850'. SPOT 25 SX CLASS C NEAT CMT PLUG ACROSS SALT TOP @ 1800' AND 8-5/8" CSG SHOE @ 1690' FROM 1850-1640'.
- PUH TO 30'. SPOT 10 SX CLASS C NEAT CMT PLUG FROM 30'-SURFACE. POOH W/ WS.
- ND BOP. RD PU. DIG OUT CELLAR AND CUT CSG 3' BELOW SURFACE. WELD STEEL PLATE ON CSG STUB. ERECT P&A MARKER WITH WELL NAME AND PLUGGED DATE. FILL CELLAR AND CLEAN SURFACE LOCATION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kaye Pollock TITLE Regulatory Technician DATE 08-16-93
TYPE OR PRINT NAME Kaye Pollock TELEPHONE NO. 915-688-2584

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE AUG 18 1993

CONDITIONS OF APPROVAL, IF ANY:

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED

BRIDGES STATE # 185 WIW
VACUUM GRAYBURG (SAN ANDRES) FIELD
LEA COUNTY, NEW MEXICO

RECOMMENDED WORKOVER PROCEDURE

1. MIRU PU. DIG PIT. FLOW WELL BACK TO PIT. ND WH. NU BOP.
2. POOH W/ 144 JTS 2-3/8" J-55 FLUORLINE TBG & 5-1/2" BAKER AD-1 PACKER & LD. RIH W/ CICR & WS TO 4400'. SET CICR @ 4400' AND CAP W/ 35' CLASS C NEAT CMT. LOAD HOLE W/ 10 PPG GELLED BRINE.
3. PUH TO 2920'. SPOT 25 SX CLASS C NEAT CMT PLUG ACROSS YATES TOP @ 2870' FROM 2920-2820'.
4. PUH TO 1850'. SPOT 25 SX CLASS C NEAT CMT PLUG ACROSS SALT TOP @ 1800' AND 8-5/8" CSG SHOE @ 1690' FROM 1850-1640'.
5. PUH TO 30'. SPOT 10 SX CLASS C NEAT CMT PLUG FROM 30'-SURFACE. POOH W/ WS.
6. ND BOP. RD PU. DIG OUT CELLAR AND CUT CSG 3' BELOW SURFACE. WELD STEEL PLATE ON CSG STUB. ERECT P&A MARKER WITH WELL NAME AND PLUGGED DATE. FILL CELLAR AND CLEAN SURFACE LOCATION.

BRIDGES STATE
WELL # 185 WIW
VACUUM GRAYBURG (SAN ANDRES) FIELD
LEA COUNTY, NEW MEXICO
CURRENT COMPLETION

E, 25, 17-S, 34-E, 2628' FNL, 100' FWL

GL = 4003'

