

## ENERGY AND MINERALS DEPARTMENT

Form C-103

Revised 10-1-78

## OIL CONSERVATION DIVISION

P.O. Box 2088

SANTA FE, NEW MEXICO 87501

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S	
LAND OFFICE	
OPERATOR	

 5a. Indicate Type of Lease  
 State ☐ Fee ☒

5. State Oil &amp; Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS

 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT  
 RESERVOIR. USE "APPLICATION FOR PERMIT-" (FORM C-101) FOR SUCH PROPOSALS.)

 XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX  
 XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX  
 XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX

 1. OIL WELL ☐ GAS WELL ☒ OTHER

7. Unit Agreement Name

 2. Name of Operator  
 Read & Stevens, Inc.

 8. Farm or Lease Name  
 Blackmar

 3. Address of Operator  
 P.O. Box 1518, Roswell, NM 88201

 9. Well No.  
 1

4. Location of Well

10. Field and Pool, or Wildcat

 UNIT LETTER P 330 FEET FROM THE South LINE AND 660 FEET FROM  
 THE East LINE. SECTION 5 TOWNSHIP 17S RANGE 37E NMPM

Wildcat

 XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX 5. Elevation(Show whether DF,RT,GR,etc.)  
 XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX 3789.6' GL

 12. County Lea  
 XXXXXXXXXXXXXXXXXXXX  
 XXXXXXXXXXXXXXXXXXXX

 Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
 NOTICE OF INTENTION TO:

 PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
 TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
 PULL OR ALTER CASING ☐  
 OTHER ☐

SUBSEQUENT REPORT OF:

 REMEDIAL WORK ☐ ALTERING CASING ☐  
 COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
 CASING TEST AND CEMENT JOB ☐  
 OTHER Acidizing ☒

Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

 3-22-84 Acidize w/6000gal 20% NE acid. Avg press 5375psi, max 5400psi, min 5200psi. Avg rate 3.8 BPM, max 4.0 BPM acid, 1.2 BPM N<sub>2</sub>, ISIP 3700psi, 5min 3600psi, 10min 3600psi, 15min 3500psi. Load 95 BBIs pad, 143 BBIs acid, 70 BBIs flush, total 308 BLW, flwd back 100 BBIs, @ 8:00pm good show of formation gas, prep to swb.

3-23-84 Swabbed 80 BBIs, 5% oil cut, good show of gas. Prep to run rods &amp; pump.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

 SIGNED [Signature] TITLE Drilling & Production Manager DATE 3-27-84

 APPROVED BY ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT SUPERVISOR

 TITLE DATE APR 30 1984

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED  
MAR 28 1984  
O.C.D.  
HOBBS OFFICE