

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name	
2. Name of Operator The Superior Oil Company		8. Field or Lease Name Mescalero Ridge	
3. Address of Operator P.O. Box 3901, Midland, Texas 79702		9. Well No. 2	
4. Location of Well UNIT LETTER <u>C</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>1580</u> FEET FROM THE <u>West</u> LINE, SECTION <u>17</u> TOWNSHIP <u>19S</u> RANGE <u>35E</u> N.M.P.M.		10. Field and Pool, or Wildcat Scharb (Bone Spring)	
15. Elevation (Show whether DF, RT, GR, etc.) 3831.6' GR		12. County Lea	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

7" Liner Detail

1-23-84 Set 7" liner @ 11,200' w/top @ 3802'. With DV tool @ 4817.60' cmtd 1-st stage-w/1130
thru sxs Class "H", .5% Halad 22A, .3% CFR-2, 3#/sx KCL. Plug down @ 0400, max pressure
1-25-84 3200#. Opened DV tool, circ, cmtd 2-nd stage w/440 sxs Class "C", 2% Ca cl. Plug
down @ 0900 hrs, closed DV tool w/2250 psi. WOC 9:00 A.M. 1-25-84 thru 9:00 A.M.
1-26-84.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>G. E. Tate</u>	TITLE <u>Division Operations Supt.</u>	DATE <u>February 2, 1984</u>
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT SUPERVISOR		
APPROVED BY _____	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		

FEB 7 1984

RECEIVED
FEB 6 1984
O.C.D.
HOBBS OFFICE