

BUREAU OF LAND MANAGEMENT
HOBBS, NEW MEXICO 88401

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. NM-24166
2. NAME OF OPERATOR POE PROPERTIES, INC.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME --
3. ADDRESS OF OPERATOR P. O. Box 9769, Fort Worth, Texas 76107		7. UNIT AGREEMENT NAME --
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' FNL & 330' FEL of Section (Unit A) (NE $\frac{1}{4}$ NE $\frac{1}{4}$)		8. FARM OR LEASE NAME SPRINKLE FEDERAL
14. PERMIT NO. --		9. WELL NO. 2
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3865' G.L.		10. FIELD AND POOL, OR WILDCAT Scharb - Wolfcamp BS
		11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA Sec. 9-19S-35E
		12. COUNTY OR PARISH Lea
		13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANE

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other) Perforating & Acidizing

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Application to re-complete this well in the Bone Springs formation was approved by the BLM on 8-7-85.

Reworking operations were commenced on 1-8-86.

On 1-9-86, Wolfcamp zone, 10544 - 10560', was plugged off by setting a bridge plug at 10500' in the 5½" casing. Bone Springs zone was perforated as follows:

9512 - 9520' 16 holes
9524 - 9530' 12 holes
9532 - 9538' 12 holes
9548 - 9602' 108 holes

On 1-10-86, Bone Springs perfs were treated with 2500 gallons of mud acid.

On 1-13-86, pumping unit was hooked up. Re-Working Operations Complete.

18. I hereby certify that the foregoing is true and correct

SIGNED

James A. Knauf

TITLE

Agent

DATE

January 29, 1986

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

FEB 3 1986

*See Instructions on Reverse Side