

Submit 3 Copies
to appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Aramis, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-28589
1. Indicate Type of Lease	STATE ☒ FEED ☐
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	Lea "TZ" State
8. Well No.	4
9. Pool name or Wildcat	Schrab/Bone Spring

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER	
2. Name of Operator Chevron U.S.A. Inc.	
3. Address of Operator P.O. Box 670, Hobbs, NM 88240	
4. Well Location Unit Letter <u>F</u> : <u>1780</u> Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>West</u> Line Section <u>16</u> Township <u>19S</u> Range <u>35E</u> NMPM Lea County	
10. Elevations (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NOTIFY NM OCD 24 HRS PRIOR TO START OF P&A OPERATIONS @ 393-6161
MIRU PU TIH W/OE TBG SPOT P&A MUD F 9365 TO 6000± RU WL CO. & RUN FREE POINT INDICATOR
CUT & PULL 5 1/2" CSG AS REQUIRED (INSTALL THREAD PROTECTORS)
SET 200' CMT PLUG ACROSS 5 1/2" CSG STUB (100' INSIDE & 100' OUTSIDE)
SET 200' CMT PLUG ACROSS SAN ANDRES F 5378 TO 5178
SET 200' CMT PLUG ACROSS 8 5/8" CSG SHOE F 4240 TO 4040
SET 200' CMT PLUG ACROSS TOP OF ANHY F 1914 TO 1714
SET 60' CMT PLUG FROM 60' TO SURFACE
INSTALL DRY HOLE MARKER
CHANGE STATUS TO PLUG & ABANDONED

** P&A MUD TO BE PLACED BETWEEN ALL CMT PLUGS

*** SEE ATTACHED SHEET FOR FORMATION TOPS

I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE <u>M. E. Akins</u> <u>8/10/90</u>	TITLE <u>Staff Drlg. Engr.</u> DATE <u>8-10-90</u>
TYPE OR PRINT NAME <u>M. E. Akins</u>	TELEPHONE NO. <u>393-4121</u>

(This space for State Use)

APPROVED BY _____	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		

FORMATION TOPS FOR LEA "TZ" STATE # 4

T/ANHY	-	1814'
BASE SALT	-	3214'
T/YATES	-	3386'
T/7 RIVERS	-	3897'
T/QUEEN	-	4648'
T/GRAYBURG	-	4948'
T/SAN ANDRES	-	5278'
T/DELAWARE	-	5651'
T/BONE SPRING	-	7890'
T/WOLFCAMP	-	10712'