

Spot 300 gal 15% NEFE 9726'. Perf 9712-26 w/2) 1/2" JHPF. Acz w/3500 gal 15% NEFE + 60 RCNB's. AP 2730, AIR 2.5 BPM. Swab. Set cmt ret @ 9704'. Lg w/150 sv Cl "H" + Halad 9 + tailed w/50 sv Cl "H" meat. Lg w/100 sv Cl "H" + cal seal. Establish inj rate, obtained 3500 psi. Lg w/54 sv below tool + in form. Run cmt + clean up. Spot 300 gal 15% NEFE 9689'. Perf 9674-80, 9683-89 w/2) 1/2" JHPF - did not perf. Sag ret - no fill on top. Circ hole clean. Perf 9673-79, 9682-88 w/2) 1/2" JHPF. Acz w/3000 gal 15% NEFE. AP 2900, AIR 2 BPM, ISIP 2700. Swab. Acz w/6000 gal gelled 15% NEFE + 12 RCNB's. AIR 6 BPM, ISIP 2100. GIHW perf sub, SN, TAC, 2 7/8" thg. GIHW pmp + rods. Electrify.