

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-77

NO. OF EXPLORATION PERMITS	
DISTRICT	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☐	Fee ☐
5. State Oil & Gas Lease No. 750469	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)		
1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER		7. Unit Agreement Name
2. Name of Operator TEXACO Producing Inc.		8. Farm or Lease Name Scharb 10 State
3. Address of Operator P.O. Box 728, Hobbs, N.M. 88240		9. Well No. 2
4. Location of well UNIT LETTER <u>K</u> <u>2310</u> FEET FROM THE <u>South</u> LINE AND <u>2310</u> FEET FROM THE <u>West</u> LINE, SECTION <u>10</u> TOWNSHIP <u>19S</u> RANGE <u>35E</u> N.M.P.M.		10. Field and Pool, or Wildcat Scharb Bone Springs
15. Elevation (Show whether DF, RT, GR, etc.) 3842.0 GL		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Rigged up. Pulled rods and pump.
- Set CIBP at 10,400', 35' cmt. on top. New PBTD 10,365.
- Set pkr. spotted w/10% acetic (9549-9350').
- Perfed w/2 JSPF 9390-9472' (53 int.).
- Acidized perfs (9390-9472') w/10,000 gal. 15% HCL-HF and 150 BS.
- POH w/pkr.
- Set CIBP at 9350', dumped 35' cmt. on CIBP.
- Spotted w/35 sx. class "H" neat plug from 7540-7640'.
- Spotted w/35 sx. class "H" neat plug from 4056-4156'.
- Spotted w/35 sx. class "H" neat plug from 1750-1650'.
- Spotted 10 sx. class "H" neat. Surface plug. Installed dry hole marker. Cleaned location. P & A.

18. I, W. E. L. L. declare and complete to the best of my knowledge and belief.

SIGNED <u>W. E. L. L.</u>	TITLE <u>Dist. Opr. Man.</u>	DATE <u>6/26/85</u>
APPROVED <u>[Signature]</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>OCT 28 1985</u>
CONDITIONS OF APPROVAL: <u>IF ANY</u>		