ENERGY	. 400	MINERALS	DEPAR	TMENT
CINERAL	6.831	WINALWETS	UCHAN	1 141514

THE PROPERTY OF THE STATE OF TH		
	<u> </u>	
DISTRIBUTION		
SANTA FE		
FILE		
U.1.G.1.		
LAND OFFICE	<u> </u>	L
OPERATOR		ĺ

OIL CONSERVATION DIVISION 87501

we, or Conica acceives	OIL CONSERVATION DI
DISTRIBUTION	P. O. BOX 2088
SANTA FE	SANTA FE, NEW MEXICO 8
FILE	
U.S.G.S.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.

USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

Form C-103 Revised 10-1	
Sa. Indicate Type of Lease	
State X Fee	
5. State Oil & Gas Lease No.	
	11
	U
7. Unit Agreement Name	
8. Form or Lease Hame	
Lea "TZ" State	
a Well No.	ì

OIL X CAB OTHER-	
2. Name of Operator Chevron U.S.A. Inc.	8. Farm or Lease Name Lea "TZ" State 9. Well No.
3. Address of Operator	
P.O. Box 670 Hobbs, NM 88240	5
(, Location of Well	19 Fysia and Pool, or Wildcan
UNIT LETTER 1790 FEET FROM THE NORTH LINE AND 900 FEET FROM	Scharb Wolfcamp
East 16 195 35E NAPH.	
15. Elevation (Show whether DF, RT, GR, etc.) 3784 GL	12. County Lea
Check Appropriate Box To Indicate Nature of Notice, Report or Oth NOTICE OF INTENTION TO: SUBSEQUENT	er Data REPORT OF:
PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS CASING TEST AND CEMENT JQB OTHER	PLUG AND ABANDONMENT
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any proposed

work) SEE RULE 1103. Propose to temporarily abandon the Wolfcamp and Bonesprings. POH with rods, pump, and tubing. Set CIBP @ 10600' and cap with 35' of cement. Set CIBP @ 9050' and cap with 35' of cement. Load hole with 9 ppg CBW with corosion inhibitor. Pressure test casing to 500 psi for 30 minutes. Leave well closed-in pending well evaluation.

ORIGINAL SIGNED BY JERRY SEXTON	JAN 2 3 1986
18. I hereby certify that the information above is true and complete to	Division Drilling Manager *** 1-22-1986

MAN STATE