

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 12-1-70

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease

State ☒Fee ☐

5. State Oil & Gas Lease No.

LG 1630

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator Gulf Oil Corp.	8. Term or Lease Name Lea "TZ" State
3. Address of Operator P. O. Box 670, Hobbs, NM 88240	9. Well No. 5
4. Location of Well UNIT LETTER <u>H</u> <u>1790</u> FEET FROM THE <u>North</u> LINE AND <u>900</u> FEET FROM THE <u>East</u> LINE, SECTION <u>16</u> TOWNSHIP <u>19S</u> RANGE <u>35E</u> N.M.P.M.	10. Is it a Dry Well, or Wildcat <u>Scholar</u> <u>Bone Spring</u>
11. Elevation (Show whether DF, RT, GR, etc.) <u>3784' GL</u>	12. County <u>Lea</u>

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUSSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐PLUG AND ABANDON ☐REMEDIAL WORK ☐ALTERING CASING ☐TEMPORARILY ABANDON ☐COMMENCE DRILLING OPNS. ☐PLUG AND ABANDONMENT ☐PULL OR ALTER CASING ☐CHANGE PLANS ☐CASING TEST AND CEMENT JOBS ☐OTHER Sq. Repair ☒OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

POH up prod eqpt. Set cmt ret @ 9575', test 2000 psi-ok. Pump 100.04
 CL"H" w/ Halad 9 + 100' of CL"H" thixotropic cmt. Sq 1900 psi. Cap ret w/ 10' cmt.
 Dil cmt + ret. Perf 9650-54' w/ (2) JH. Pump 1000 gals 15% NEFE. Swab. Set
 cmt ret @ 9652'. Sq w/ 100.04 CL"H" w/ Halad 9 + 100' of CL"H" thixotropic cmt.
 Sq 2000 psi. Cap ret w/ 10' cmt. Dil cmt + ret. Perf 9646-56' w/ (2) JH. Spot
 500 gals 15% NEFE. Swab. Set RBP @ 9406', test 2000#-ok. Perf 9114-18'
 w/ (4) JH. Spot 300 gals 15% NEFE. Swab. Set ret @ 9048'. Spot 200.04
 CL"H", sq 2200#. Dil cmt + ret. Spot 300 gals 15% 9105-8800'. Perf 9101-05'
 w/ (2) JH. Swab. No show oil or gas. Will recomplete. Half comp.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R.D. Pite TITLE AREA ENGINEER DATE 1-11-85

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT SUPERVISOR

TITLE

DATE JAN 15 1985

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JAN 14 1985

U.S. DEPT.
HOBBS OFFICE