Submit 3 Copies to Appropriate District Office

## State of New Mexico 1 29, Minerals and Natural Resources Departme.

Form C-103 Revised 1-1-89

**DISTRICT I** P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION P.O. Box 2088

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-28677

5.	Indicate Type of Lease			
	STATE FEE X	_		
_	State Oil & Con Lance No.			

DISTRICT III	STATE			
1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil & Gas Lease No.			
SUNDRY NOTICES AND REPORTS ON WELLS  ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	TO A  7. Lease Name or Unit Agreement Name  MESCALERO RIDGE B COM			
1. Type of Well: OIL GAS WELL X WELL OTHER				
2. Name of Operator	8. Well No.			
MOBIL PRODUCING TX & NM INC.	1			
3. Address of Operator	9. Pool name or Wildcat			
BOX 633, MIDLAND, TX 79702	SCHARB BONE SPRINGS			
4. Well Location				
Unit Letter O: 801 Feet From The SOUTH Line and	1839 Feet From The EAST Line			
Section 17 Township 19S Range 35E	NMPM LEA County			
10. Elevation (Show whether DF, RKB, RT, GR, etc.)  ZERO C KB (18' AGL) GL:3826				
11. Check Appropriate Box to Indicate Nature of Not	tice, Report, or Other Data			
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WO	ORK ALTERING CASING			
TEMPORARILY ABANDON CHANGE PLANS COMMENCE D	DRILLING OPNS. PLUG AND ABANDONMENT			
PULL OR ALTER CASING CASING TEST	AND CEMENT JOB			
OTHER: OTHER:				
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dowork) SEE RULE 1103.	ates, including estimated date of starting any proposed			

1. MIRU WO UNIT. UNSEAT PUMP, POOH W/RODS & PUMP. NU BOP, TEST. RELEASE TAC, POOH W/TBG & TAC. 2. RIH W/TBG & CIBP. SET CIPB @ 8250' & 50' (5 SKS) CMT CAP. POOH W/TBG.

P & A (WITHOUT CASING RECOVERY)

3. MIRU WIRELINE UNIT. PERF SQUEEZE HOLES 4 SPF 4150-4152'.

- 4. SET CMT RETAINER @4050', SQUEEZE 45 SKS BENEATH RETAINER, BEHIND 5 1/2" & DUMP 5 SKS ON TOP RETAINER.
- 5. CIRC WELL W/10 PPG GELLED BRINE.
- 6. SPOT 150' (41 SKS) CMT PLUG ACROSS 13 3/8" SHOE, 345-495'.
- 7.Spot 100' (27 sks) surface plug, surface 100'.
- 8. Cut csg 3' below ground, weld on plate and P & A marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE Shulay load	MOBIL EXPLORATION & PRODUCING U.S. INC.  TITLE AGAGENT FOR MOBIL PRODUCING TX & HM INC.	DATE 11-30-89		
TYPE OR PRINT NAME SHIRLEY TODD		TELEPHONE NO. 688-2585		
(This space for State Use): PMGINIT SIGNED	SUPERVISOR	DEC 0 4 1989		
APPROVED BY	TITLE	DATE		
CONDITIONS OF APPROVAL, IP ANY:	THE TOWARDS A MANAGEMENT OF THE STATE OF THE			

ADDIGNATIONS TOP A TOP

TO BE APPROVED

RECEIVEL

DEC #1 1989

OCD HOBBS OFFICE