

RECEIVED		
DISTRIBUTION		
DATE		
BY		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☒
1. Lease No.
LC-2363

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO GRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL <input type="checkbox"/> GAS <input type="checkbox"/> OTHER	7. Unit Agreement Name
2. Name of Operator JEG ENTERPRISE	8. Form or Lease Name Arco State
3. Address of Operator P.O. Box 100, Artesia, NM 88210	9. Well No. 1
4. Location of Well UNIT LETTER <u>N</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>2120</u> FEET FROM THE <u>West</u> LINE, SECTION <u>16</u> TOWNSHIP <u>18-S</u> RANGE <u>32-E</u> NMPM.	10. Field and Pool, or Wildcat Young Bone Spring
15. Elevation (Show whether DF, RT, GR, etc.) 3773.5 GR.	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
PLUG OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and completing work. SEE RULE 1103.

Intend to Plug and Abandon as Follows:

Place Cast Iron Bridge at 8864 ft. (Top Perf. 8964')

Place 35 ft. cement on top of CIBP.

Cut 5 1/2" casing at 8000 ft. Place 100 ft. cement plug one half inside of 5 1/2" X and one half above 5 1/2" cut off.

Place a 100 ft. plug at 5600 ft. (Top of Delaware)

Place a 100 ft. Plug (one half in Bottom of 9 5/8" and one half out of bottom of 9 5/8" at 4013 ft.

Place a 100 ft. plug from 700 ft. to 800 ft.

Place a 10 sack plug at surface plus Dry Hole Marker.

and restore location.

I certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED James Guy TITLE James Guy, Agent DATE 8-21-85

DRILLING SECTION

2008 8 21 1985

APPROVED BY: TITLE