

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLI
(Other instructions
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ <u>Dry</u>	5. LEASE DESIGNATION AND SERIAL NO. <u>NM 40456</u>
2. NAME OF OPERATOR <u>Gulf Oil Corp.</u>	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR <u>P. O. Box 670, Hobbs, NM 88240</u>	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface <u>2310' FNL + 1980' FWL</u>	8. FARM OR LEASE NAME <u>Sprinkle "B" Fed</u>
14. PERMIT NO.	9. WELL NO.
15. ELEVATIONS (Show whether DF, RT, GR, etc.) <u>3912' GL</u>	10. FIELD AND POOL, OR WILDCAT <u>Under Bone Springs</u>
	11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA <u>Sec. 1-T18S-R32E</u>
	12. COUNTY OR PARISH <u>Lea</u>
	13. STATE <u>NM</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Set 50 sack plug 8460'-8310', set 50 sack plug 7800'-7650',
set 125 sack plug 6150'-6000', set 75 sack plug 5400'-5250',
set 50 sack plug 4700'-4600', set 100 sack plug 3850'-3750'-tag
set 30 sack plug 550'-450'. Set 50' surf plug. Install
dry hole marker. Clear + clean loc. Verbal approval
given by Bob Pitschke (BZM).

18. I hereby certify that the foregoing is true and correct

SIGNED RDP

TITLE AREA ENGINEER

DATE 10-28-84

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE CARESSAD RESOURCE AREA

DATE 1-21-85

*See Instructions on Reverse Side