

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. OF ☒ oil ☐ gas well ☐ other

2. NAME OF OPERATOR

Harvey E. Yates Company

3. ADDRESS OF OPERATOR

P. O. Box 1933, Roswell, New Mexico 88201

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below)

AT SURFACE: 660' FSL & 660' FSL

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH: Same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE REPORT OR OTHER DATA

REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT ON:
TEST WATER SHUT-OFF	☐
FRACTURE TREAT	☐
SHOOT OR ACIDIZE	☒
REPAIR WELL	☐
PULL OR ALTER CASING	☐
MULTIPLE COMPLETE	☐
CHANGE ZONES	☐
ABANDON*	☐
(other)	☐

5. LEASE

NM-036852

6. INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Young Deep Unit 3 Federal

8. FARM OR LEASE NAME

9. WELL NO.

1

10. FIELD OR WILDCAT NAME

North Young Bone Springs

11. SEC., T., R., M. OR BLK. AND SURVEY OR AREA

Sec. 3, T-18S, R-32E

12. COUNTY OR PARISH 13. STATE

Dea NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

10/11/84 Perf @ 9108' to 9120' w/2 spf. Spot 200 gal 20% SRA.
10/13/84 Acidize w/3000 gals 20% SRA & ballsealers.
10/15/84 Set CIPR @ 9078' w/35' amt on top. FBTD 9040'. Perf Bone Springs @ 8456' to 8470'.
10/18/84 Spot 200 gals 20% SRA.
10/20/84 Sqz perfs 8456' - 8470' w/100 sxs class "H", .15% Hald-9, & .13% CFR.
10/23/84 Perf from 8456' to 8463' w/2 spf.
10/24/84 Spot 200 gal SPA acid.
10/26/84 Sqz perfs w/150 sxs class "H" w/.15% Hald-9 & .13% CFR-2, put 100 sxs in perfs & 50 sxs in csc.
11/1/84 Acidize w/3000 gal 20% SRA & flush w/fresh water.
11/15/84 RIH w/Hydrojet tool & 2 3/8" tool. Set @ 8453'. Spot 6 bbls acid. & 250 gal 15% HCL.

Subsurface Safety Valve: Make and Type

Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED *[Signature]* TITLE V.E. Operations DATE 11/26/84

ACCEPTED FOR RECORD (space for Federal or State office use)

APPROVED BY *[Signature]*
CONDITIONS OF APPROVAL

TITLE

DATE

NOV 27 1984

[Signature]

NEW MEXICO

*See Instructions on Reverse Side

11/17/84 GIH W/SN, 4 jts tail pipe, tbg anchor & 250 jts 2 3/8" tbg. Set @ 8474'.
11/18/85 GIH W/2" X 1 1/4" X 20' X 24' pump. Hang well on production.

O.C.D.
HOBBS OFFICE

NOV 28 1984

RECEIVED