

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
P. O. BOX 1980

SUBMIT IN TRIPLICATE  
Other Instructions

Budget Bureau No. 1004-0135  
Expires August 31, 1985

3. LEASE DESIGNATION AND SERIAL NO.

NM-59044

4. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Cavalcade "21" Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Young Wolfcamp

11. SEC., T., S., M., OR BLK. AND  
SURVEY OR AREA

Section 21, T18S, R32E

12. COUNTY OR PARISH

Lea

13. STATE

N.M.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Cavalcade Oil Corporation

3. ADDRESS OF OPERATOR

P.O. Box 16187, Lubbock, Texas 79490

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

660' FSL & 1650' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3760.6 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

6/19/85 - 6/24/85

Set 5 1/2" CIBP @ 10,750' to isolate Lower Wolfcamp perforations between 10,758' - 10,808'.  
325' of cement on top of plug. Set 5 1/2" CIBP @ 10,483' to isolate Upper Wolfcamp  
perforations between 10,565' - 10,581'. 225' of cement was placed on top of  
plug. Cut 5 1/2" casing off @ 5575'. Set cement plug @ 6932' w/11 sx. of Class "C"  
neat cement. Set 2nd cement plug across 5 1/2" stub. Cemented w/50 sx. Class "C"  
neat. Balanced plug with 10# brine spot cement plug @ 5650'. Shut well in for  
48 hrs. Come back and tag cement plug @ 5485'. Prepare to attempt a completion  
inside 8 5/8" csg. Plugging instructions were received by the BLM before  
plugging operations began. The BLM was also notified of time and place for  
witness purposes.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Drilling & Production Mgr.

DATE 6/26/85

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

\*See Instructions on Reverse Side

JUL 2 1985

CARLSBAD, NEW MEXICO