

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 12-1-78

CO. OPERATOR RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

3a. Indicate Type of Lease	
State ☐	Fee ☒
3. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. Unit Agreement Name	
2. Name of Operator Harvey E. Yates Company		8. Term of Lease (Date)	
3. Address of Operator P.O. Box 1933, Roswell, New Mexico 88201		9. Well No. 1	
4. Location of Well UNIT LETTER <u>E</u> <u>1650</u> FEET FROM THE <u>North</u> LINE AND <u>330</u> FEET FROM THE <u>West</u> LINE, SECTION <u>25</u> TOWNSHIP <u>17S</u> RANGE <u>37E</u> N.M.P.M.		10. Field and Pool, or Whichever Hobbs Channel Bone Spring Hobbs Channel Wolfcamp	
11. Elevation (Show whether DF, RT, GR, etc.) 3705.8 GL		12. County LEA	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPER. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work; SEE RULE 1103.

- 9-14-88 Load hole w/10# brine, GIH w/overshot & catch fish, pull tbg to top of rods, LD remaining rods and pump.
- 9-15-88 Kill well w/10# Brine, POH w/tbg, anchor, SN, set CIBP @ 9950', 35' cmt on top of CIBP. GIH w/tbg open ended, spot 100' plug @ 9350-9450', and 8415-8515', pull 40 stds.
- 9-16-88 Tag plug @ 8230', spot 100' plug @ 5622 to 5522, POH w/tbg, ND BOP, tbg head, weld on lift nipple, shoot pipe off @ 4800'.
- 9-17-88 POH w/5 1/2" csg, GIH w/tbg open ended, spot 100' plug @ 4850 to 4750
- 9-18-88 Tag cmt @ 4720, spot 100' plug @ 4650 to 4550, WCC, tag cmt @ 4530, spot 100' plug @ 2200 to 2100', spot 50' plug @ surface, cut off csg. head and weld on dry hole marker. Well P & A 9-18-88.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Reservoir Engineer/Manager DATE September 20, 1988

APPROVED BY [Signature] TITLE OIL & GAS INSPECTOR DATE NOV 03 1988

CONDITIONS OF APPROVAL, IF ANY:

E