

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

3a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER		7. Unit Agreement Name
2. Name of Operator Harvey E. Yates Company		8. Farm or Lease Name Howry "25"
3. Address of Operator P. O. Box 1933, Roswell, New Mexico 88201		9. Well No. 1
4. Location of Well UNIT LETTER <u>E</u> <u>1650</u> FEET FROM THE <u>North</u> LINE AND <u>330</u> FEET FROM THE <u>West</u> LINE, SECTION <u>25</u> TOWNSHIP <u>17S</u> RANGE <u>37E</u> N.M.P.M.		10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) <u>3705.8</u>		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11/20/84 Drop Bar & Perf 11,355' to 11,376' w/2 JSPF (42 Holes).
11/21/84 Acid w/500 gal 15% MSR-100.
11/25/84 Spot 250 gal 15% MSR-100.
11/28/84 Spot 500 gal 15% MSR-100.
12/13/84 Acidize w/3000 gal 20% MSR-100 w/60 RCNBS.
12/18/84 Perf 10,551 to 10,555'; 10572' to 10,577' & 10,584'-86' (2 SPF, 25 holes).
12/20/84 Acidize w/3000 gal 20% MSR-100 w/50 RCN Ball Sealers.
12/27/84 Set CIBP @ 10,650' & Dump 35' cmt on top.
12/28/84 Set CIBP @ 10,540' & dump 35' cmt on top (New PBTD 10,505'). GIH & perf squeeze holes @ 10,070' (4 shots) & @ 9965' (4 shots) GIH w/cmt retainer & set @ 9980'.
12/29/84 Tag up retainer @ 9980'.. Mix 75 sxs class "H" w/.7% TIC & .2% FLAC. Displace to retainer (Minus 2 Bbls) POO retainer 80'. Reverse out excess cmt (30 sxs) Clean up hole.
01/01/85 Tag cmt @ 9923': Drill to retainer @ 9980', drill cmt to 10,020'. Circ hole clean
01/03/85 Finish drilling cmt & continue in hole to 10,150'.
01/04/85 Perf @ 10,054' to 10,070' & 10,080' to 10,094' (2 SPF, 62 holes).
01/08/85 Set CIBP @ 9950' & dump 35' cmt on top.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>A. M. [Signature]</u>	TITLE <u>Drlg. Superintendent</u>	DATE <u>2/13/85</u>
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR		
APPROVED BY _____	TITLE _____	DATE <u>FEB 18 1985</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

FEB 15 1985

OFFICE
HONORARY

01/09/85 Perf @ 9404' to 9408', 9440' to 9450' (2 SPF, 30 holes).
01/12/85 Spot 250 gal 15% MSR @ 9450'.
01/15/85 Acidize w/1500 gal 15% MSR-100 & 60 RCNBS.
01/17/85 Sqz perfs @ 9404' to 9408' & 9440' to 9450' w/50 sxs "H" w/.2% TIC & .2% FLAC.
01/18/85 Set CIBP @ 9350'. Perf 8486' to 8515' (59 holes).
01/19/85 Spot 250 gal 15% MSR across perfs @ 8486' to 8515'.
01/20/85 Acidize w/1500 gal 20% MSR & 60 ball sealers.
01/22/85 Acidize w/5000 gal 20% MSR-100 & 60 ball sealers.
01/26/85 Acidize w/7500 gal 20% MSR & BAF as diverters.
02/06/85 GIH w/pump. Hang well on production.