

(November 1983)
(Formerly 9-331)

DEPARTMENT OF THE INTERIOR (Other Instructions on
BUREAU OF LAND MANAGEMENT verse side)

Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	2. NAME OF OPERATOR Harvey E. Yates Company	3. ADDRESS OF OPERATOR P. O. Box 1933, Roswell, New Mexico 88201	4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1650' FNL & 1980' FEL	5. LEASE DESIGNATION AND SERIAL NO. NM-9018	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	7. UNIT AGREEMENT NAME Young Deep Unit	8. FARM OR LEASE NAME 40	9. WELL NO. 15	10. FIELD AND POOL, OR WILDCAT North Young Bone Springs	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 9, T-18S, R-32E	12. COUNTY OR PARISH Lea	13. STATE NM
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, ST, CK, etc.) 3830' GL											

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETION

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANE

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(Note: Report results of multiple completion on Well Completion or Recombination Report and Log form.)

17. DESCRIBE LOGGED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

4/21/85 Perf @ 8957' to 8912' (1 SPF, 8 holes).
4/23/85 Acidize w/2000 gal & 16 ball sealers.
4/24/85 Frac perfs w/60,000 gal EZ Frac 60 & 10% CO2 w/134,000# 20/40 sd.
4/26/85 Perf 8660' to 8789' (1 spf, 13 holes). Set RBP @ 8855'. Acidize w/3500 gal & 26 ball sealers.
4/27/85 Frac perfs w/97,500 gal EZ Frac 60 & 216,000# 20/40 sd.
5/01/85 Set CIBP @ 8630'. GIH & perf 8525' to 8530' & 8516' to 8548' (2 SPF, 16 holes). Acidize w/450 gal & 35 ball sealers.
5/03/85 GIH & perf @ 8432' to 8444' & 8470' to 8475' (2 SPF). Set RBP @ 8500'.
5/04/85 Acidize w/4500 gal 20% SRA & 68 ball sealers. POH w/RBP.
5/08/85 Turn well over to production.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Drlg Superintendent

DATE 5/13/85

(This space for Federal or State office use)

APPROVED BY ACCEPTED FOR RECORD
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

MAY 14 1985

*See Instructions on Reverse Side

RECEIVED
MAY 15 1985
HOBBS OFFICE