

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator ARCO Oil and Gas Company	8. Farm or Lease Name Emma Lawrence
3. Address of Operator P.O. Box 1610, Midland, Texas 79702	9. Well No. 1
4. Location of Well UNIT LETTER <u>I</u> <u>660</u> FEET FROM THE <u>East</u> LINE AND <u>1980</u> FEET FROM THE <u>South</u> LINE, SECTION <u>23</u> TOWNSHIP <u>17 S</u> RANGE <u>38E</u> NMPM.	10. Field and Pool, or Wildcat Southeast Knoles Wolfcamp
15. Elevation (Show whether DF, RT, GR, etc.) 3663.3 GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
		OTHER <u>Add perfs & treat Wolfcamp and San Andres.</u> <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-14-85. RUPU. POH w/CA.
10-16-85. Set CIBP @ 9760. Dump 30' cmt on top.
10-17-85. Perf WC f/9319-9404. Set pkr @ 9232. Acddz w/1500 gal
10-19-85. Swbd 128 BLW & 177 BFW w/no show of oil or gas.
10-20-85. Set CIBP @ 9270. Dump 30' cmt on top.
10-21-85. Spot 10# MLF f/9240-7700. Spot 25 sx cmt plug f/7700-7490. Perf 4 holes @ 6350.
10-22-85. Set CR @ 6307. Sqzd perfs @ 6350 w/400 sx "H" cmt. TS indicate TOC @ 4550'.
10-23-85. Perf SA @ 5839-6242 (24 holes). Acddz w/4000 gal
10-25-85. Swab test 4 days. Rec 934 BFW, No show of oil or gas.
10-31-85. Set CIBP @ 5800' & dumped 35' cmt on top. Perf f/5350-5406(18 holes.) Acddz w/1800 gal.
11-1-85. Swab test w/ no show of oil or gas. RDPU. S1 for evaluation.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Ken W. Gosnell 915 688-5672
TITLE Engr. Tech. Spec. DATE 6-11-86

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE JUN 17 1986

CONDITIONS OF APPROVAL, IF ANY: