

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Sun Exploration & Production Company	8. Farm or Lease Name New Mexico X-19 State
3. Address of Operator P.O. Box 1861 Midland, Texas 79702	9. Well No. 1
4. Location of Well UNIT LETTER <u>P</u> <u>330</u> FEET FROM THE <u>South</u> LINE AND <u>330</u> FEET FROM THE <u>East</u> LINE, SECTION <u>19</u> TOWNSHIP <u>17S</u> RANGE <u>36E</u> NMPM.	10. Field and Pool, or Wildcat Undesignated-Abo
15. Elevation (Show whether DF, RT, GR, etc.) 3873.8	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PU to 9162' West spot 100' cmt plug fm 9162' to 9062' w/Western spot 100' cmt plug fm 9162 to 9062 w/22 sks C1 H + 3/4% CF-1 PU to 8730' spot 100' cmt plug fm 8730' to 8630' w/22 sks C1 H + 3/4% CF-1 PU to 6645'. Spot 100' cmt plug fm 6645 to 6545 w/22 sks C1 C neat cmt, PU to 4975 spot 100 cmt plug fm 4975-4875 w/22 sks C1 C neat cmt. Pull up to 4450. Spot 100' cmt plug fm 3550 to 3450 across 8-5/8 csg seat w/86 sks CL C neat cmt. PU to 1965 spot 100' cmt plug fm 1965 to 1865 w/36 sks C1 C neat cmt. Fin POH. LD DP ND BOPS. Cut off csg & wellhead 5' BGL. set 10 sks surf. plug of C1 C neat, Weld on steel plate & dry hole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Wilma Reyes TITLE Sr. Accounting Assistant DATE 5/10/85

ORIGINAL SIGNED BY JERRY SEXTON

DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

MAY 11 1985