

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

3a. Indicate Type of Lease	
State ☒	Fee ☐
3. State Oil & Gas Lease No.	
LG 1784	
7. Unit Agreement Name	
8. Farm or Lease Name	
Amoco East 2 State	
9. Well No.	
4	
10. Field and Pool, or Wildcat	
North Young Bone Spring	
12. County	
Lea	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒	GAS WELL ☐	OTHER ☐
2. Name of Operator		
Harvey E. Yates Company		
3. Address of Operator		
P.O. Box 1933, Roswell, New Mexico 88202		
4. Location of Well		
UNIT LETTER <u>0</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM		
THE <u>East</u> LINE, SECTION <u>2</u> TOWNSHIP <u>18S</u> RANGE <u>32E</u> N.M.P.M.		

15. Elevation (Show whether DF, RT, CR, etc.)

3889.2 KB

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐
PULL OR ALTER CASING ☐	OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒	ALTERING CASING ☐
COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proceed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-17-87 POH w/tbg anchor & SN.
12-18-87 Set CIBP @ 8600'. Abrasa jet 2 cuts @ 8444' & wash w/350 gal 20% SRA.
12-20-87 Acidize w/100 gals 20% SRA. Unable to breakdown. Rev. acid out.
12-22-87 Abrasa jet 2 cuts @ 8444' again and jet w/500 gals.
12-23-87 Acidize w/1500 gals 20% SRA.
12-29-87 Acidize w/5000 gals 20% SRA w/N₂ and 5000 gals overflush.
12-31-87 Perf 2 JSPF from 8397-8410' (13'- 27 holes)
01-01-88 Acidize w/250 gals 20% MSR to break down perfs.
01-05-88 Acidize w/2500 gals 20% SRA.
01-06-88 Acidize w/10,000 gals 20% MSR-100 and 5000 gals overflush.
01-08-88 GIH w/SN, anchor & tbg to test perfs. 8444 to 8397' (OA). Turn over to pumper.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Production Manager/Engineer DATE January 8, 1988

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY [Signature] TITLE [Signature] DATE JAN 11 1988

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
JAN 4 1988
O-20
HOBBS OFFICE