

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-29294 ✓
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	
VIERSEN	
8. Well No.	1
9. Pool name or Wildcat	SHIPP STRAWN

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator PENNZOIL EXPLORATION AND PRODUCTION COMPANY	
3. Address of Operator P. O. BOX 50090 - MIDLAND TX 79710-0090	
4. Well Location Unit Letter <u>I</u> : <u>2130</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>4</u> Township <u>17-S</u> Range <u>37-E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3791' RKB - 3772' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11/20/92 thru 12/08/92: Pull & lay down 2-7/8" tubing - Set CIBP at 11080' w/35' cement plug on top - TOC at 11045' - Circ. hole w/brine mud - Spot 25 sx cement plug from 8313' to 8163' - Spot 25 sx cement plug from 5935' back to 5785' - Pull out of hole & rig up casing cutter - Cut 5-1/2" casing at 4254' & rec. 104 jts. 5-1/2" casing - Pump 50 sx. Class -C- plug at 4254' - Pull out of hole - Trip in hole to top of cement - Did not tag plug - Pumped 50 bbls. LCM Pill and 50 sx Class -C- cement plug - WOC - Trip in hole to top of cement at 4274' - Had 20' of cement plug - Pump 50 sx Class -C- cement plug from 4274' to 4174' - Spot 35 sx. Class -C- cement plug from 2063' to 1963' - Pumped 10' surface plug - Cut off 13-3/8 head - Weld on Dry Hole Marker - Well was P & A on 12/08/92
" FINAL REPORT "

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Roy R. Johnson

TITLE

Sr. Accountant

DATE

01/15/93

TYPE OR PRINT NAME

ROY R. JOHNSON

915-689-8907

TELEPHONE NO.

(This space for State Use)

OIL & GAS INSPECTOR

FEB 25 1993

APPROVED BY

Emily M. Hill

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JAN 19 1993

100-100000-100