

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. V-1355	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Exxon Corporation Attn: Permits Supervisor		8. Farm or Lease Name New Mexico EX State
3. Address of Operator P.O. Box 1600, Midland, TX 79702		9. Well No. 1
4. Location of Well UNIT LETTER <u>A</u> <u>330</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM <u>East</u> LINE, SECTION <u>9</u> TOWNSHIP <u>17S</u> RANGE <u>37E</u> NMPM.		10. Field and Pool, or Wildcat Undes. Midway ABO
15. Elevation (Show whether DF, RT, GR, etc.) GR 3768		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-28-88 Set CIBP @ 8775', cap w/ 35' cmt.  
7-29-88 Cut off 5 1/2" csg @ 4250'. Layed down cut off csg.  
7-30-88 Displace hole with 9.5 ppg salt gel from 8730'. Spot 50 sx CLH from 7700' to 7448'  
WOC and tagged plug at 7438'. Spot 50 sx CLC @ 6500' to 5997'. Spotted 50 sx CLC at 4250'  
8-1-88 Tagged plug set at 4250' at 4240'. Reset plug from 4240' to 4000' with 56 sx CLC.  
Spot 50 sxs of CLC from 2150' to 1900'. Spot 50 sx CLC from 550' to 300'. Spot 10 sx CLH  
from 100' to surface.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Stephen Johnson</u>	TITLE <u>Administrative Specialist</u>	DATE <u>08-17-88</u>
APPROVED BY <u>R.A. Keller</u>	TITLE <u>OIL &amp; GAS INSPECTOR</u>	DATE <u>11-2-88</u>
CONDITIONS OF APPROVAL, IF ANY:		