Form 3160-5 (JUNE 1990)	UNITED SY, WES DEPARTMENT OF THE INTERIOR N.M. OIL CONS. DIVISIO BUREAU OF LAND MANAGEMENT 1625 N. French Dr.					Expires: March 31, 1993	
SUNDRY NOTICES AND REPORTS ON WRODDS, NM 88240						5. Lease Designation and Serial No. NM-57285	
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals						6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE						or CA, Agreement Designation	
1. Type of Well							
Oil Gas Well Well X Other						8. Well Name and No.	
2. Name of Operator						Stivason Federal #3	
STRATA PRODUCTION COMPANY 3. Address and Telephone No. P. O. Box 1030						9. API Well No. 30-025-29544	
Roswell, New Mexico 88202-1030 505-622-1127					10. Field an	d Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 330' FNL & 1650' FEL						l Queen	
Section 33-19S-34E						11. County or Parish, State Lea County, New Mexico	
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, O							
	TYPE OF SUBMISSION TYPE OF ACTION						
Notice of Intent			Abandonment			hange of Plans	
			Recompletion		м	lew Construction	
Subsequent	t Report		Plugging Back		N N	Ion-Routine Fracturing	
Final Abandonment Notice			Casing Repair			Vater Shut-Off	
			Altering Casing	Clean Out		onversion to Injection	
		~	OTHER	Clean Out	(Note: Report	hispose Water results of multiple completion on Well	
13. Describe Proposed or Co	mpleted Operations (Clea	rly state all pertinent	details, and give pertinent of the second se	dates, including estimated date of starting a s and zones pertinent to this work.)*		r Recompletion Report and Log form.) ork. If well is	
		incastition and the ve		and zones permanent to this work.			
<u>01/31/02:</u>	<u>01/31/02:</u> MIRU.						
<u>02/01/02:</u>	02/01/02: Release pkr. NUBOP. TOH w/tbg. LD pkr. Prep to clean out.						
		-1/2" bit and scraper. Tag up @ 4480'. Perfs 4527' - 4 nit and clean out.			4556'. P	U 4 stds. Prep to	
<u>02/05/02:</u>	/05/02: Tag up @ 4480'. Drlg. Clean out to TD. Circ hole clean.						
<u>02/06/02:</u>	TOH w/tbg. 1 @ 1800#. Pr	IH w/5-1/2" tension pkr. Circ w/2% KCL and pkr fluid.			. Set pkr	. Pump in fluid	
- · · · · · · · · · · · · · · · · · · ·		. Pump solvent to perfs.			15	 	
02/20/02: Pump 1500 gal 15% acid across perfs. Drop injection pressure from Put on injection.				n 1 80 0#	to 550≇ at .5 BPM.		
14. I hereby certify that the for	oregoing is true and corre	ct			<u> </u>		
Signed	6X Barit		Production Re	cords	Dator	04/05/02	
(This space for Federal of						199	
Approved by (OR) Conditions of approval, if	fonu	ID R. GLAS	0		Date		
approval, il	ÄPR 15 20)02					
Title 18 U.S.C. Section 1001, ma representations as to any matter v	akes it a crime for any per- within its jurisdiction.	son knowingly and will	ully to make to any departme	ent or agency of the United States any false, fi	ctitious or fraudu	alent statements or	
		SS * See I	nstruction on Revers	se Side		F3160-5.WK1	
<u>} * *</u>	<u>tatottionitet</u>					K	

, ---



TH :01 MA 8- 89A 2002

BUREAU O, CHICE MOMT.