Form 3160-5 (November 1983) (Formerly 9-331)  DEPARTMEN' OF THE INTERIOR verse side)  BUREAU OF LAND MANAGEMENT	Budget Bureau No. 1004-0135 Expires August 31, 1985 5. LEASE DESIGNATION AND SERIAL NO NM-8675
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reserved 40  Use "APPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
OIL GAS	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Mewbourne Oil Company	8. FARM OR LEASE NAME Federal "H"
3. ADDRESS OF OPERATOR P. O. Box 7698, Tyler, Texas 75711	9. WELL NO.
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*  See also apace 17 below.)  At surface  330' FSL & 330' FEL	10. FIELD AND POOL, OR WILDCAT QUETECHO Plains - Upper Bone Springs 11. SEC., T., E., M., OR BLK. AND BURVEY OR ARMA 22-18S-32E
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
API #30-025-29628 3757' GR	Lea N.M.
Check Appropriate Box To Indicate Nature of Notice, Report, or	
TEST WATER SHUT-OFF  PULL OR ALTER CASING  MULTIPLE COMPLETE  SHOOT OR ACIDIZE  REPAIR WELL  CHANGE PLANS  WATER SHUT-OFF  FRACTURE TREATMENT  SHOOTING OR ACIDIZING  (Other) Set Phoc  (Note: Report resu	REPAIRING WELL  ALTERING CASING  ABANDONMENT®  ABANDONMENT®  ABANDONMENT®  X  Its of multiple completion on Well  appletion Report and Log form.)
3/16/86 - Ran 1.68 FS, 4.74' shoe joint, 1.45' FC,	15 centralizers,
43 joints 5-1/2" 17# N-80 LT&C (1781.04') 17# K-55 LT&C (5902.76') 29 joints 5-1/2" (1237.50'). Total 8968.53'. Set at 8960'. with 500 sacks of "H" with .8% CF-14 (1st of PSL "H" with 1/4# celloseal and 200 sa CF-14 (2nd stage). PD to 8915.13' at 12:1 Circ. 45 sacks 1st stage. PD to 7005.81' Circ. 31 sacks. DV tool at 7005.81'.	17# N-80 LT&C Western cemented Stage) and 1000 sacks Cks of "H" with .6% 5 A.M. 3/16/86.
17# K-55 LT&C (5902.76') 29 joints 5-1/2" (1237.50'). Total 8968.53'. Set at 8960'. with 500 sacks of "H" with .8% CF-14 (1st of PSL "H" with 1/4# celloseal and 200 sa CF-14 (2nd stage). PD to 8915.13' at 12:1 Circ. 45 sacks 1st stage. PD to 7005.81'	17# N-80 LT&C Western cemented Stage) and 1000 sacks Cks of "H" with .6% 5 A.M. 3/16/86.
17# K-55 LT&C (5902.76') 29 joints 5-1/2" (1237.50'). Total 8968.53'. Set at 8960'. with 500 sacks of "H" with .8% CF-14 (1st of PSL "H" with 1/4# celloseal and 200 sa CF-14 (2nd stage). PD to 8915.13' at 12:1 Circ. 45 sacks 1st stage. PD to 7005.81' Circ. 31 sacks. DV tool at 7005.81'.  ACCEPTED FOR RECORD  MACCEPTED FOR RECORD	17# N-80 LT&C Western cemented Stage) and 1000 sacks Cks of "H" with .6% 5 A.M. 3/16/86.

DATE \_\_\_