

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-29651
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-1688
7. Lease Name or Unit Agreement Name Buckeye, 8601 JV-P
8. Well No. 1
9. Pool name or Wildcat Vacuum, Grayburg - San Andres
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3,870' GR 3,882' RKB

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Dry
2. Name of Operator BTA OIL PRODUCERS
3. Address of Operator 104 South Pecos, Midland, Texas 79701
4. Well Location Unit Letter -D- : 330 Feet From The North Line and 330 Feet From The West Line Section 29 Township 17-S Range 36-E NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Proposed Procedure

Set CIBP @ 4900' w/ 35 sx cmt on top
25 sx @ 4445' (50' below 8 5/8" shoe)
Cut & pull 5 1/2" csg @ 1200'
25 sx across 5 1/2" stub
25 sx @ 452' (50' below 13 3/8" shoe)
10 sx @ Surface
Install Dry Hole Marker

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE R. D. Boyce TITLE Administrative Supervisor DATE 9/8/89

TYPE OR PRINT NAME R. D. BOYCE

TELEPHONE NO. 915/682-3753

(This space for State Use)

APPROVED BY ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

CONDITIONS OF APPROVAL, IF ANY:

DATE

SEP 11 1989