Submit 3 Copies To Appropriate District State of New Mexico Form C-103 Office Revised March 25, 1999 Energy, Minerals and Natural Resources District 1 WELL API NO. OIL CONSERVATION DIVISION 1625 N. French Dr., Hobbs, NM 87240 30-025-29711 District II 2040 South Pacheco 811 South First, Artesia, NM 87210 5. Indicate Type of Lease Santa Fe, NM 87505 District III STATE X FEE 1000 Rio Brazos Rd., Aztec, NM 87410 State Oil & Gas Lease No. District IV 2040 South Pacheco, Santa Fe, NM 87505 E8563 7. Lease Name or Unit Agreement Name: SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH Consolidated State PROPOSALS.) 1. Type of Well: Gas Well Other Oil Well 8. Well No. Name of Operator Fasken Oil and Ranch, Ltd. 9. Pool name or Wildcat Address of Operator Shipp (Strawn) 303 W. Wall Ave., Suite 1800, Midland, TX 79701-5116 Well Location 660 __feet from the ___north__ line and ___2128 __feet from the __west Unit Letter C : line NMPM Lea Township 17S Range 37E County Section 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3778.7' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. **PLUG AND CHANGE PLANS TEMPORARILY ABANDON ABANDONMENT** CASING TEST AND **MULTIPLE PULL OR ALTER CASING CEMENT JOB** COMPLETION OTHER: OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Fasken Oil and Ranch, Ltd. proposes to plug and abandon the subject well as follows. Set 5 1/2" CIBP at 10850' and circ well w/ 10 ppg mud-laden fluid. Spot 25 sx Class "H" on top of CIBP. Spot 25 sx Class "H" at 8800". - TAG Spot 25 sx Class "H" at 6300'. Free point 5 ½" casing and cut off at 4800' (estimated). Spot 25 sx Class "C" 50' below 5 1/2" cutoff. Tag Plug. TO BE A MIC Spot 25 sx Class "C" at 4333'. Spot 40 sx Class "C" at 2000'. Hobbs Spot 30 sx Class "C" at 448'. OCD Spot 10 sx Class "C" surface plug. Cut off and weld on plat with 4" OD marker 4' above ground level. Clean location. I hereby certify that the information above is true and complete to the best of my knowledge and belief. TITLE Regulatory Affairs Coordinator _____DATE __3/19/03__ SIGNATURE Telephone No. (915) 687-1777 Type or print name Jimm D. Carlile

> ORIGINAL SIGNED BY GARY W. WINNTLE

OC FIELD REPRESENTATIVE HISTARE MANAGER

_DATE MAR 2 6 2003

(This space for State use)

Conditions of approval, if any:

APPPROVED BY