

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-77

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ For ☐

5. State Oil & Gas Lease No.
B-1565

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator Texaco Producing Inc.	8. Farm or Lease Name New Mexico "BM" State
3. Address of Operator P. O. Box 728, Hobbs, New Mexico 88240	9. Well No. 1
4. Location of Well UNIT LETTER O 330 FEET FROM THE South LINE AND 1652 FEET FROM East THE LINE, SECTION 16 TOWNSHIP 17S RANGE 36E NMPM.	10. Field and Pool, or Wildcat Lovington San Andres West
15. Elevation (Show whether DF, RT, GR, etc.) 3875.6' KB	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU. TOH w/Pm and rods. NU BOP, TOH w/tbg.
2. Set 5-1/2" CIBP @ 5375', cap w/35' cmt. New PBTD @ 5340'.
3. Run production equipment.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 397-3571

SIGNED <u>J. A. Head POW</u>	TITLE <u>Hobbs Area Superintendent</u>	DATE <u>8-5-88</u>
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR		
APPROVED BY _____	TITLE _____	DATE <u>AUG 2 8 1988</u>
CONDITIONS OF APPROVAL, IF ANY:		