

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

WELL API NO. 30-025-29841
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-1125
7. Lease Name or Unit Agreement Name State "3"
8. Well No. 1
9. Pool name or Wildcat Shipp Strawn

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Amerind Oil Company Limited Partnership	
3. Address of Operator 415 W Wall Suite 500, Midland TX 79701	
4. Well Location Unit Letter B : 679 Feet From The North Line and 2130 Feet From The East Line Section 3 Township 17S Range 37E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR 3771'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6/20/95 Set CIBP @ 11,150'. Displaced wellbore w/10 lb/gal brine gel.
Spot 25 sx plug @ 11,150'
30 sx plug @ 8,133'
30 sx plug @ 6,346'
Cut 5-1/2" csg @ 4110' & rec 97 jts. Displaced well bore w/brine mud.
Spot 60 sx plug @ 4,250'. Tagged TOC @ 3,933'.
Spot 45 sx plug @ 2,053'.
Set 10 sx surface plug @ 20'.
Cut & remove wellhead
Weld on dry hole marker.
Well P & A 6/23/95

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE JAMES E. YELEY TITLE Agent DATE 6/27/95
TYPE OR PRINT NAME James E. Yeley TELEPHONE NO. 915/682-8217

(This space for State Use)

APPROVED BY Billy E. Prichard TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUN 26 1985

UCD HUBB
OFFICE

RECEIVED

JUN 26 1985

UCD HUBB
OFFICE