SUNDRY NOTICES AND REPORTS (Do not use this form for proposals to drill or to deepen or plus use "APPLICATION FOR PERMIT—" for such well X well other other harvey E. Yates Company ADDRESS OF OPERATOR P.O. Box 1933, Roswell, New Mexico Location of well (Report location clearly and in accordance with an See also space 17 below.) At surface 1650' FSL & 990' FWL	ON WELLS g back to a different reservoir. a proposals.) DEC 10 10 43 MI CARLES. SOUR AREA HEAD CHARTEI	NM-63365 6. IF INDIAN, ALLOTTEE 37 UNIT AGREEMENT HAM 8. FARM OR LEASE NAME Tank 1 Federal 9. WELL NO.	(B	
OIL X GAS WELL OTHER NAME OF OPERATOR Harvey E. Yates Company ADDRESS OF OPERATOR P.O. Box 1933, Roswell, New Mexico Location of well (Report location clearly and in accordance with an See also space 17 below.) At surface	DEC 10 10 43 MI CARLES AREA HEAD CHARTEI 88202	JUNIT AGREEMENT HAN 8. FARM OR LEAST NAME Tank 1 Federal	18	
OIL X GAS WELL OTHER NAME OF OPERATOR Harvey E. Yates Company ADDRESS OF OPERATOR P.O. Box 1933, Roswell, New Mexico Location of Well (Report location clearly and in accordance with an See also space 17 below.) At surface	CARLES COURTER AREA HEADLUARTER	Tank 1 Federal		
Harvey E. Yates Company ADDRESS OF OPERATOR P.O. Box 1933, Roswell, New Mexico Location of Well (Report location clearly and in accordance with an See also space 17 below.) At surface	AREA HEADLUMÄTEI 88202	Tank 1 Federal	<u> </u>	
P.O. Box 1933, Roswell, New Mexico Location of Well (Report location clearly and in accordance with an See also space 17 below.) At surface	88202	Tank I rederal		
LOCATION OF WELL (Report location clearly and in accordance with an See also space 17 below.) At surface	88202		<u> </u>	
At surface	DE State Peculyaments &	#1		
1650' FSL & 990' FWL	See also space 17 pelow.) At surface		10. PIELD AND POOL, OR WILDCAT	
1650' FSL & 990' FWL		North Young Sone		
		SURVEY OR AREA		
PERMIT NO. 15 ELEVATIONS (Show whether)	DF, RT, GR, etc.)	Sec. 1, T18S,	R32E	
30-025-29888	3900.0 GL	Lea	NM	
Check Appropriate Box To Indicate	Nature of Notice, Report, or O	ther Data		
NOTICE OF INTENTION TO:		ENT REPORT OF:		
TEST WATER SHUT-OFF PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WE	LL	
FRACTURE TREAT RIDOUT OR ACIDIZE ABANDON®	FRACTURE TREATMENT SHOOTING OR ACIDIZING	ALTERING CAS	·	
REPAIR WELL CHANGE PLANS	(Other) Spud, Surfa		X	
Other) DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertine proposed work. If well is directionally drilled, give subsurface local		of multiple completion on tion Report and Log form		
12/3/87 Spud well @ 2:30 pm, TD @ 4 Ran 418 ft of 13 3/8, 48#, Cemented w/425 sks Class " sks to pit, Plug down @ 1:0 600 psi/30 min-Held ok	J-55 csg, set @ 414 ft 'C" w/2% CaCl & 1/4# flo	oceal. Circ 80		
12/7/87 TD @ 2850 ft, Ran 2855 ft o Cemented w/1100 sks LiteWat Plug down @ 5:00 am 12/7/87 for 30 min-Held ok. As per. N.M. Yawng j 250 s	e & 200 sks Class "C" v 7, WOC 12 hrs, Test csg	w/2% CaCl, to 1200 psi		
1,		SJS		
	A STATE OF THE STA	- F		
	SJS			
hereby certify that the foregoing is true and correct				
·	illing Superintendent	DATE 12/8/87		
This space for Federal or Suite office use)				