

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

|                        |  |
|------------------------|--|
| NO. OF COPIES RECEIVED |  |
| DISTRIBUTION           |  |
| SANTA FE               |  |
| FILE                   |  |
| U.S.G.S.               |  |
| LAND OFFICE            |  |
| OPERATOR               |  |

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

3a. Indicate Type of Lease  
State ☒ Fee ☐

5. State Oil & Gas Lease No.  
41487

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.

|                                                                                                                                                                                                         |                                                  |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------|
| 1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-                                                                                       | 7. Unit Agreement Name                           |
| 2. Name of Operator<br>Texaco Producing Inc.                                                                                                                                                            | 8. Farm or Lease Name<br>N.M. "O" State (Nct-1)  |
| 3. Address of Operator<br>P.O. Box 728, Hobbs, New Mexico 88240                                                                                                                                         | 9. Well No.<br>26                                |
| 4. Location of Well<br>UNIT LETTER <u>M</u> <u>990</u> FEET FROM THE <u>South</u> LINE AND <u>990</u> FEET FROM<br>THE <u>West</u> LINE, SECTION <u>36</u> TOWNSHIP <u>17-S</u> RANGE <u>34-E</u> NMPM. | 10. Field and Pool, or WHdcat<br>Vacuum Glorieta |
| 15. Elevation (Show whether DF, RT, GR, etc.)<br>4014' KB                                                                                                                                               | 12. County<br>Lea                                |

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐  
OTHER ☐

REMEDIAL WORK ☒  
COMMENCE DRILLING OPS. ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER ☐

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐  
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU. Pull pump and rods. Install BOP. Pull tubing.
2. Set 5-1/2" cement retainer on wireline at 6020'.
3. Sting into retainer with tubing. Squeezed perms at 6046'-6098' with 50 sx class "H", 15.6 ppg. Maximum pressure 150 psi. Reversed out 4 sacks cement.
4. Spot 200 gallons 10% acetic acid at 5818'-6018'. POH.
5. Perforate Glorieta 2 SPI at 5975'-5983', 5989'-5992', 5996'-5999' (17 intervals, 34 holes).
6. Set packer at 5842'. Acidize with 2500 gals 15% NEFE and 50 ball sealers. AIR 3 bpm, maximum pressure 2600 psi, ISIP 0.
7. Swab. POH with packer and tubing.
8. Perforate Glorieta 2 SPI at 5907'-5931', 5938'-5954' (42 intervals, 84 holes).
9. Set RBP at 5965' and packer at 5847'. Acidize with 6000 gals 15% NEFE and 7000 scf nitrogen and 125 ball sealers. AIR 3.2 bpm at 750 psi. Maximum pressure 900 psi, ISIP 100 psi.
10. Swab. Run production equipment. On 24 hour OPT 9-11-87: pumped 404 BO, 58 BW, GOR 646

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. Gerhardt 393-4031 TITLE Area Superintendent DATE 9-15-87

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT 1 SUPERVISOR

TITLE \_\_\_\_\_ DATE SEP 18 1987

CONDITIONS OF APPROVAL, IF ANY: