

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

EXEMPT AN UNCLASSIFIED
(Other instructions on the
reverse side)

Expires August 31, 1985
5. LEASE DESIGNATION AND SERIAL NO.

NM 67987

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT ASSIGNMENT NAME

8. FARM OR LEASE NAME

Jade Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

East Shugart Delaware

11. SEC., T., R., N., OR BLK. AND
SURVEY OR AREA

Sec. 19: T18S, R32E

12. COUNTY OR PARISH 13. STATE

Lea

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

CONFIDENTIAL

OIL WELL ☒ GAS WELL ☐ OTHER ☐

1. NAME OF OPERATOR

Siete Oil & Gas Corporation

2. ADDRESS OF OPERATOR

P. O. Box 2523, Roswell, New Mexico 88201

3. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)

At surface

Unit Letter F, 1650' FNL & 1650' FWL, SE/4 NW/4

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, OR, etc.)

3712' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

Production Casing

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

7/01/87 L & M Rig #1 T.D. 7 7/8" hole to 5500'. Ran 133 jts. of
5 1/2" 15.5# casing (5503.54') set @ 5500' KB.

7/02/87 Cemented in two stages (DV Tool @ 2985')

First stage - 560 sks. DS II, 3# D-44, .5% D-127, circulated
50 sks. to the pit. Plug down @ 5:15 a.m.
Second stage - 600 sks. DLW III, 8# D-44, 1/4# D-29,
circulated 47 sks. to the pit. Plug down @ 10:30 a.m.
W.O.C.

ACCEPTED FOR RECORD

JUL 14 1987

SJS

CARLEBAD NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

L. D. Justice

TITLE Drlg. & Prod. Vice Pres. DATE 7/8/87

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side