

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill-stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	NAME	TOP	
					MEAS. DEPTH	TRUE VERT. DEPTH
Penrose	3860	3868	Sand; No tests	B/Salt T/Queen T/Grayburg	2235	+1485
Grayburg	4310	4370	Sand, Dolomite; No tests		3563	+ 157
Grayburg	4448	4474	Sand; No tests		3979	- 259