Submit 3 Copies To Appropriate District State of New Mexico	Form C-103
District I Energy, Minerals and Natural Resources	Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 88240 District II	WELL API NO.
811 South First, Artesia, NM 88210 OIL CONSERVATION DIVISION	30-025-30102
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410	5. Indicate Type of Lease STATE V FEE
District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	B=2076
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	
PROPOSALS.)	Central Unit Vacuum
1. Type of Well: Oil Well Gas Well X Other Injector	
2. Name of Operator	8. Well No.
Texaco Exploration & Production, Inc.	223
3. Address of Operator	9. Pool name or Wildcat
P. O. Box 3109, Midland, TX 79702 4. Well Location	Vacuum Grayburg, S.A.
4. Well Location	
Unit Letter K : 1821 feet from the South line and 1330 feet from the West line Section 25 Township 17S Range 34E NMPM Lea County 10. Elevation (Show whether DR, RKB, RT, GR, etc.)	
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK ALTERING CASING REMEDIAL WORK ALTERING CASING	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	K ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT	
PULL OR ALTER CASING MULTIPLE CASING TEST A CEMENT JOB	ND
OTHER: OTHER:	
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.	
1. RIH Tag TOC on CIBP @ 4155' (Set on 8/21/95) Displace hole w/MLF	
9.5# Brine w/25# gel P/BBL	Displace note w/MLF
2. Spot 40 Sx plug 3800'-3600' (Oueen)	
3. Spot 40 Sx plug 2800'-2600' (B-Salt, Yates)	
4. Spot 40 Sx plug 1650'-1450' (13 3/8" shoe. T	-Salt) Tag @ 1336'
5. Spot 40 Sx plug 450'-250' (20' shoe) Tag @ 1	05'
6. Circ Cmt 30' to Surf w/10 Sx. Install dry h	ole marker. 8/14/01
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE TITLE MANAGER	DATE 8/14/01
Type or print name Jimmy BAGLEY	Telephone No. 915 683 4996
(This space for State use)	
APPPROVED BY Conditions of approval, if any:	