

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-30110
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-1687
7. Lease Name or Unit Agreement Name Marathon State
8. Well No. 1
9. Pool name or Wildcat Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Tom Schneider	
3. Address of Operator 505 N. Big Spring St. Suite 204 Energy Sq. Bld. Midland, TX	
4. Well Location Unit Letter B : 1300 Feet From The North Line and 1980 Feet From The East Line Section 27 Township 17-S Range 36-E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3835.6 GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose plugging well as follows;

cement plug #1 5060-5210 (150') 15 sx.
cement plug #2 4530-4400 (150') 15 sx.
cement plug #3 1675-1825 (150') 18 sx.
cement plug #4 0-100 (100') 10 sx., dryhole marker inserted in top plug
TD 5210, intermediate casing left in well, production casing 5½" 15.5#
& 17#, set 0-5220 with 400 sx. estimated cement top @ 1750', est.
recover 1750' 5½" csg.
Spot bottom plug, WOC, tag, pump 9.5# mud, pull up spotting plugs until
last plug set.
Would like to start operations around middle May

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Thomas Schneider TITLE _____ DATE 5-8-90

TYPE OR PRINT NAME _____ TELEPHONE NO. _____

(This space for State Use)
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

MAY 14 1990

THIS DOCUMENT IS NOT TO BE USED FOR ANY OTHER PURPOSES
EXCEPT AS SPECIFICALLY AUTHORIZED BY THE STATE OF NEW MEXICO
FOR THE PURPOSES OF THE OIL CONSERVATION DIVISION