

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lesse	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Charles B. Gillespie, Jr.	8. Farm or Lease Name Shipp 'DA'
3. Address of Operator P.O. Box 8 Midland, TX 79702	9. Well No. 1
4. Location of Well UNIT LETTER H 2130 FEET FROM THE North LINE AND 660 FEET FROM THE East LINE, SECTION 10 TOWNSHIP 17-S RANGE 37-E NMPM.	10. Field and Pool, or Wildcat Humble City Strawn
15. Elevation (Show whether DF, RT, GR, etc.) 3752.4' G.L.	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. (1-11-88) Reached total depth 11,630'. Ran open hole logs.

2. (1-13-88) Pumped cement plugs as follows:

40 sx plug from 11448' to 11348'
40 sx plug from 9432' to 9332'
40 sx plug from 8190' to 8090'
45 sx plug from 6803' to 6703'
45 sx plug from 4522' to 4422'
30 sx plug from 2200' to 2100'
30 sx plug from 492' to 392'
10 sx plug from 30' to surface

Installed 4" dry hole marker.

3. Will notify OCD at Hobbs after clean-up complete.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED: David Husty TITLE: Production Manager DATE: 1/14/88
APPROVED BY: [Signature] TITLE: OIL & GAS INSPECTOR DATE: JUN 10 1988
CONDITIONS OF APPROVAL, IF ANY:

E