

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

LAND CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole	7. Unit Agreement Name
2. Name of Operator Nearburg Producing Company	8. Farm or Lease Name Baker 7M
3. Address of Operator P.O. Box 31405 Dallas TX 75231	9. Well No. 1
4. Location of Well UNIT LETTER M 1300 FEET FROM THE South LINE AND 400 FEET FROM THE West LINE, SECTION 7 TOWNSHIP 17S RANGE 38E NMPM.	10. Field and Pool, or Wildcat S. Humble City Strawn
15. Elevation (Show whether DF, RT, GR, etc.) 3720.9' GR	12. County LEA

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-12-88: Drilled to total depth of 11,940'. (7 7/8" hole)
4-13-88: Logging
4-14-88: Logging
4-15-88: P.&A. as follows:
Plug #1 30 sacks 11,446' to 11,546' 100'
Plug #2 30 sacks 8,778' to 8,878' 100'
Plug #3 30 sacks 6,700' to 6,800' 100'
Plug #4 30 sacks 4,617' to 4,717' 100'
Plug #5 30 sacks 2,100' to 2,200' 100'
Plug #6 10 sacks surface to 30' 30'
Install dry hole marker

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Eddie J. Schuch</u>	TITLE <u>Operations Coordinator</u>	DATE <u>9-19-88</u>
APPROVED BY <u>Darwin Smith</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>AUG 1 - 1988</u>

CONDITIONS OF APPROVAL, IF ANY: