

Form 3160-5
(November 1983)
Formerly 9-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE
(Other instructions on re-
verse side)

Form approved
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO. NM 55145	
2. NAME OF OPERATOR Harvey E. Yates Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P.O. Box 1933, Roswell, New Mexico 88202		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Unit letter D, 330' FNL & 990' FWL		8. FARM OR LEASE NAME Querecho Plains 22 Federal	
14. PERMIT NO. 30-025-30266		9. WELL NO. 1	
15. ELEVATIONS (Show whether DP, RT, GN, etc.) 3781.8 GL		10. FIELD AND POOL, OR WILDCAT Young Bone Spring	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 22, T18S, R32E	
		12. COUNTY OR PARISH Lea	13. STATE NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	☐	WATER SHUT-OFF	☐
FRACTURE TREAT	☐	FRACTURE TREATMENT	☒
RHOUT OR ACIDIZE	☐	SHOOTING OR ACIDIZING	☐
REPAIR WELL	☐	(Other)	☐
PULL OR ALTER CASING	☐	REPAIRING WELL	☐
MULTIPLE COMPLETE	☐	ALTERING CASING	☐
ABANDON*	☐	ABANDONMENT*	☐
CHANGE PLANS	☐		

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

12-08-88 Perf 6129 - 6183 (OA) 1 SPF, set 5 1/2 RBP 1ok set @ 6500',
Acidize w/1300 gals, 7 1/2% NEFE & 20 BS

12-11-88 Acidize w/2000 gals, 15% NEFE & 25 bbls overflush, treated @ 4 BPM.

12-14-88 Frac perfs 6129 - 83 (OA) w/30,000 gals WF 30 & 40,000# 16/30 Ottawa.

12-15-88 Set anchor @ 6003, SN @ 6362'.

12-16-88 Hang well on & turn over to pumper.

RECEIVED
JAN 4 11 47 AM '89
CARLSBAD
AREA

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Production Manager/Engineer DATE 12-29-88

(This space for Federal or State office use)

APPROVED BY: [Signature] TITLE DATE

COMMISSIONER OF APPEALS, IF ANY:

ACCEPTED FOR RECORD
DATE JAN 17 1989

3000
30010 2280

*See Instructions on Reverse Side

SJS
CARLSBAD, NEW MEXICO

RECEIVED

RECEIVED

JAN 20 1989

DEC 30 1988

OCD
HOBBS OFFICE

OCD
HOBBS OFFICE