

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instruction  
verse side)

Form approved:  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Harvey E. Yates Company	8. FARM OR LEASE NAME Querecho Plains 22 Fed.
3. ADDRESS OF OPERATOR P.O. Box 1933, Roswell, New Mexico 88202	9. WELL NO. #1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 330' FNL & 990' FWL	10. FIELD AND POOL, OR WILDCAT Wildcat-Bone Springs
14. PERMIT NO. 30-025-30266	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 22, T18S, R32E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3781.8 GL	12. COUNTY OR PARISH Lea
	13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANT

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Completion

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

- 5/17/88 Perforate Strawn @ 11670-90, Acidize w/15,500 gals HCL  
Test well for production.
- 5/29/88 Set CIBP @ 10530 w/35 ft of cement (New PBTD @ 10495')  
Perforate Wolf Camp @ 10342-48 & 10364-70, Acidize w/4500 gals HCL.  
Test well for production.
- 6/7/88 Set CIBP @ 10050 w/35 ft of cement (New PBTD @ 10015')  
Perforate Bone Springs @ 9700-9712 & 9762-66, Acidize w/750 gals HCL.  
Test well for production.
- 6/16/88 Set CIBP @ 9680 (New PBTD), Perforate Bone Spring @ 9147-9370,  
Acidize w/3500 gals HCL, Frac w/100,000 gals WF 45 BS w/20% CO<sub>2</sub>  
and 200,000# 20/40 sand  
Test well for production.

18. I hereby certify that the foregoing is true and correct

SIGNED A.M. Young N.M. Young

TITLE Drilling Superintendent

DATE 7/7/88

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_

ACCEPTED FOR RECORD

DATE \_\_\_\_\_

JUL 22 1988

\*See Instructions on Reverse Side

SJS  
CARLSBAD, NEW MEXICO

RECEIVED

JUL 22 1988

MOBILE, AL